



LEPELLE NORTHERN WATER

CONDITION ASSESMENT ON 9.5KM PIPELINE AT PHALABORWA WTW.

COASTTECH PROJECTS (PTY) LTD.

15 March 2024



Submitted by:

Coasttech Projects Pty Ltd.
50 Electron Avenue
Isando
Inospace Electron Exchange
Unit 2
1601

Submitted to:

Lepelle Northern Water
01 Landros Mare Street
Polokwane
0699

DOCUMENT CONTROL SHEET


| DOCUMENT DESCRIPTION | | | | | | | |
|----------------------|--|------------|------------|----------|------------------------|--------|--|
| Business Unit: | Coasttech Projects Technical Department Tel: 010 510 2679 nmkhize@coasttech.africa | | | Client: | Lepelle Northern Water | | |
| Date: | 15 March 2024 | Report No: | PWTW-CA001 | Phase: | | Task: | |
| Title: | Condition Assessment on 9,5 Km Pipeline at Phalaborwa WTW | | | Version: | 0 | Pages: | |

| DOCUMENT REVISION HISTORY | | | | |
|---------------------------|---------|----------|--------------------------------------|--------------------|
| Date | Version | Page | Description of Change | Author |
| 15 March 2024 | 0 | | Original Submission | Coasttech Projects |
| 24 April 2024 | 001 | 18,19,25 | Information on Lining Rehabilitation | Coasttech Projects |
| | | | | |
| | | | | |

| DOCUMENT (all electronic copies unless indicated otherwise) | | | DISTRIBUTION | |
|--|------------------------|--------|---------------|--|
| Name | Organisation | Copies | Date | |
| Shudu Ratshibvumo | Lepelle Northern Water | 1 | 15 March 2024 | |

DOCUMENT APPROVAL SHEET

DOCUMENT APPROVAL

| Action | Position | Name | Signature | Date |
|-------------|------------------------|-----------------|---|---------------|
| Produced by | Coasttech Projects | Ntuthuko Mkhize |  | 15 March 2024 |
| Approved by | Lepelle Northern Water | | | |

Executive Summary

Coasttech Projects (Pty) Ltd, was appointed by Lepelle Northern Water, to undertake a Condition Assessment for a pipeline that transports portable water from the Phalaborwa Water Treatment Works to the Phalaborwa Mining Company (PMC).

The scope of works comprised of in-line inspections (ILI) as well as the External Corrosion Direct Assessment (ECDA) Surveys. The In-line inspection technique that was employed was the CCTV Inspection, there was provision for leak detection survey also, but due to the pipeline being decommissioned and drained, only the CCTV survey could be performed. The ECDA was fully explored in accordance with the NACE SP0502 guidelines and in the following order:

Direct Current Voltage Gradient Survey, locating coating defects anomalies, locations and potential gradient measure.

The external corrosion protection system of the buried pipelines consists of an external pipe coating system and theft/vandalism bonded Cathodic Protection. In general, the external pipeline coating system consists of sections with the bitumen and replacement sections.

The DCVG survey data was collected electronically capturing pertinent pipeline and right of way features which were location, time and date stamped with respect to the WGS 84, GPS co-ordinate system.

This systematic approach to the survey techniques enabled the successful correlation and analysis of the DCVG data to show sections where areas of coating defects and gradient potentials were located, classifying coating defects and areas for immediate, scheduled or monitored action to be taken. Test stations and right of way areas requiring attention, are referenced and summarised herein.

Contents

| | | |
|------------|---|-----------|
| 1 | Background & Introduction | 7 |
| 1.1 | Objectives | 7 |
| 1.2 | Scope Of Works - Condition Assessment Surveys..... | 7 |
| 2 | Abbreviations | 8 |
| 3 | Reference Documentation | 9 |
| 4 | Condition Assessment Methodologies as per the SOW | 10 |
| 4.1 | Part 1 : In-Line Inspection (ILI)..... | 10 |
| 4.2 | Part 2: External Corrosion Direct Assessment (ECDA) | 10 |
| 5 | Part 1 : In-Line Inspection (ILI) Evaluation Summary | 12 |
| 6 | Part 2: External Corrosion Direct Assessment (ECDA) Evaluation Summary | 12 |
| 6.1 | ECDA Survey System Setup | 12 |
| 6.2 | Direct Current Voltage Gradient (DCVG) Survey..... | 12 |
| 6.3 | Direct Inspections | 13 |
| 7 | ECDA Classification of Findings | 14 |
| 7.1 | Pre-Assessment (ECDA Region Identifications)..... | 14 |
| 7.2 | Pipe To Soil Potentials and ACVG Findings | 14 |
| 7.3 | DCVG Coating Defect Classification..... | 14 |
| 7.4 | Soil Resistivity Survey and Profile | 15 |
| 7.5 | Direct Inspection Findings..... | 15 |
| 8 | Summary Of ECDA Indirect Survey Findings | 15 |
| 8.1 | Soil Resistivity Survey..... | 15 |
| 8.2 | Summary Of DCVG Findings | 16 |
| 8.3 | ROW and Test Station Findings | 16 |
| 8.4 | DCVG Results..... | 17 |
| 8.5 | NDT Results..... | 17 |
| 8.6 | Direct Inspection Results | 17 |
| 8.7 | Excavation 01 | 17 |
| 8.8 | Excavation 02 | 17 |
| 9 | Conclusion | 18 |
| 9.1 | In-Line Inspection (ILI) CCTV Survey Conclusion | 18 |
| 9.2 | External Corrosion Direct Assessment (ECDA) Survey Conclusion..... | 18 |
| 9.3 | Overall Conclusion | 19 |
| 10 | Recommendations | 19 |
| 11 | Appendices..... | 20 |
| 11.1 | Appendix 1 : CP Assets and Valve Chambers..... | 21 |
| 11.2 | Appendix 2 : ECDA Surveys CP Results | 22 |
| 11.3 | Appendix 3 : Metal Loss Assessment Results | 23 |
| 11.4 | Appendix 4 : CCTV Survey Results | 24 |
| 11.5 | Appendix 5 : Trenchless Pipeline Relining Technology | 25 |

List of Tables

| | |
|--|----|
| Table 1: Abbreviations | 8 |
| Table 2: Summary of DCVG classifications and findings | 14 |
| Table 3: Relationship between resistivity and corrosivity | 15 |
| Table 4: Summary of classifications and Direct Inspection Requirements | 15 |
| Table 5: Summary of the DCVG results | 16 |
| Table 6: Summary of the DCVG Severe/Immediate and Scheduled areas of Concern | 16 |

List of Figures

Figure 1 : Water Flooded Valve Chamber.

1 Background & Introduction

Coasttech Projects (Pty) Ltd, was appointed by Lepelle Northern Water, to undertake a condition assessment of a 560mm diameter pipeline, spanning over 9,5 kilometres from the Phalaborwa Water Treatment Works transporting portable water to the water utility's clients within the Phalaborwa area. The pipeline had been decommissioned due to frequent bursts that had been experienced over a period of time which was seen as a cause for concern. With the pipeline being decommissioned, the scheme finds itself operating in a risky manner as it is operating without any redundancy. A failure that can occur on the current operating pipe system can easily translate to a total downtime, without any backup plan. It was then seen as of utmost importance to undertake this condition assessment that can help shed light into the possible causes of the bursts and to get the overall structural integrity of the pipeline.

1.1 Objectives

The paramount objective of the condition assessment was to determine the possible causes of the bursts as well as to assess the structural integrity of the pipeline in order to provide reliable data that can assist in the formulation of future repair strategies.

1.2 Scope Of Works - Condition Assessment Surveys

The scope of work for the pipeline condition assessments surveys entailed the following;

- ☐ Leak Detection Testing
- ☐ CCTV Inspection
- ☐ Coating Defect Survey
- ☐ Corrosion Assessment on Valve Chambers
- ☐ Soil Resistivity Survey (Soil Corrosivity Survey)
- ☐ Pipe to Soil Potential and Visual Assessment on Cathodic Protection (CP) Structures.
- ☐ Stray Current Analysis (Electromagnetic Current Attenuation Survey)
- ☐ Metal Loss/ Wall Thickness Testing

The pipeline details are listed below:

| | |
|----------------|----------------------------------|
| Pipe Diameter | : 560mm |
| Pipe Thickness | : 6mm |
| Pipe Length | : 9,5 Km |
| Coating | : Bituminous Pipe Coating System |
| Pipe Age | : 50+ Years |

2 Abbreviations

Table 1: Abbreviations

| Abbreviation | Description |
|--------------|---|
| AC | Alternating Current |
| API | American Petroleum Institute |
| CCTV | Closed Circuit Television |
| CH | Valve Chamber |
| CP | Cathodic Protection |
| CSE | Copper Sulphate Electrode |
| CT | CP Structures |
| DC | Direct Current |
| DCVG | Direct Current Voltage Gradient Survey |
| ECDA | External Corrosion Direct Assessment |
| HT | High Tension |
| HV | High Voltage |
| IF | Insulating Flange |
| IJ | Insulation Joint |
| KP | Kilometer Point |
| MP | Mark post |
| NACE | National Association of Corrosion Engineers |
| PCM | Pipeline Current Mapping |
| PSP | Pipe to Soil Potential |
| RC | Road Crossing |
| RV | River |
| RL | Railway line |
| ST | Stream |
| SVT | Servitude |
| TP | Test Post |
| TRU | Transformer Rectifier Unit |
| ROW | Right of Way (Servitude) |

3 Reference Documentation

The condition assessment was carried out in accordance with international standards and cited references below:

- NACE SP 0169 – Control of External Corrosion on Underground or Submerged Metallic Piping Systems.
- NACE RP 0177- 95 Mitigation of alternating current and lightning effects on Metallic Structures and corrosion control systems.
- NACE SP 0200 – Steel Cased Pipeline Practices.
- NACE standard (TM0102-2002)- Current Drain Test
- NACE TM 0497 – Measurement Techniques Related to Criteria for Cathodic Protection on Underground or Submerged Metallic Piping Systems
- NACE RP 0502 – Pipeline External Corrosion Direct Assessment Methodology.
- BSI – Standard BS 7361, Part 1, “Cathodic Protection: Code of Practice for Land and Marine Applications”.
- ASME B31.3/B31G

4 Condition Assessment Methodologies as per the SOW

Coasttech Projects (Pty) Ltd. commissioned a condition assessment methodology by segmenting the scope of works into two parts , one that assesses the inside of the pipeline, and the other that concentrates on the external part of the pipeline and also looks at the environment surrounding the pipeline. The two groups are identified as Part 1 : In-line inspection (ILI) and part 2 : External Corrosion Direct Assessment (ECDA).

4.1 Part 1 : In-Line Inspection (ILI)

In-Line Inspection (ILI) is achieved by performing a non-intrusive leak detection and CCTV inspection to detect and confirm the presence of leaks and determine the lining condition of the steel pipeline. Due to the pipeline being decommissioned, it proved to be impossible to carry out the leak detection testing as the method requires water to be flowing in the pipe, The only in-line inspection method that was successfully performed was the CCTV inspection.

The CCTV inspection was performed in the following steps,

- Pre-Assessment
 - Collection of chainages information.
 - identifying access and exit points for the robotic crawler(Valves).
- Insertion & Monitoring
 - Launching of the robotic crawler from the access point.
 - Controlling of camera levels, angles and speed of robotic crawler.
- Footage Analysis & Reporting
 - Using the pictures and footage , collecting and collation of data with reference to locations of the pipeline.

4.2 Part 2: External Corrosion Direct Assessment (ECDA)

External Corrosion Direct Assessment (ECDA) is a structured process that is intended at improving safety by assessing and reducing the impact of external corrosion on pipeline integrity, by identifying and addressing corrosion activity and repairing corrosion defects and remediating the cause. ECDA proactively seeks to prevent corrosion defects from growing to a size that is large enough to impact structural integrity. The ECDA techniques that were employed in this project were the coating defect survey, corrosion assessment on valve chambers, soil resistivity survey, visual assessment on cp structures, pipe to soil potential survey, stray current analysis and metal loss/ wall thickness testing.

The ECDA process contains four (4) Stages that we followed;

- Pre-Assessment
 - Collection of historic and current data
- Indirect Inspection
 - Covers the above-ground inspections to identify and define severity of coating faults, areas where corrosion activity has occurred or may be occurring, and other anomalies.
- Direct Examination
 - Analysis of the indirect inspection data to select sites for excavations and pipe surface evaluation.
 - The data from direct examination are combined with prior data to identify and assess the impact of external corrosion on the pipeline.
 - Evaluation of pipeline coating performance .
 - Corrosion defects repairs.
 - Mitigation of corrosion protection faults.
- Post Assessment
 - Analysis of data collected from the previous three (3) steps, to assess the effectiveness of the ECDA process and determine re-assessments intervals.

5 Part 1 : In-Line Inspection (ILI) Evaluation Summary

The CCTV survey was commissioned and a survey report is appended to this progress report and labelled as follows:

- ☐ Inspection Report (CCTV)
- ☐ Chainage Corrosion Pictures
- ☐ CCTV Videos

From the CCTV survey report, it is evident from the pictures and videos that most parts of the lining system have underwent blistering, cracking, peeling, rust spotting and rust staining. The major contributing factor to the lining defects is ageing of the pipeline.

6 Part 2: External Corrosion Direct Assessment (ECDA) Evaluation Summary

6.1 ECDA Survey System Setup

The Lepelle Northern Water Phalaborwa water treatment works pipelines are protected using impressed current CP systems (ICCP), unfortunately most of them were found to be vandalized, through critical bonds to other pipelines with applied CP. The surveys were conducted in the direction of product flow.

A temporary CP system was set up and interrupted using GPS synchronised current interrupters. Potential measurements carried out at the pipe end points conferred that the temporary CP systems could be interrupted with an increased output due to the high attenuation noted.

6.2 Direct Current Voltage Gradient (DCVG) Survey

The DCVG survey was carried out according to the test station run summary as presented in Appendix 2. The coating defects were located, flagged and the potential gradients and the data was collected electronically along with pertinent pipeline and Right of Way (ROW) features along each test run. The datalogger has a built in GPS antenna that enables GPS positioning and data to be collected which is based on the WGS 84 longitude and latitude system with each data point collected. This enables a permanent location stamp of the feature to be captured that enables future location and traceability (Accuracy is within 2 – 3 metres). When viewing the data on Google Earth, spatial errors can be up to 5 metres.

The weather during the DCVG / ACVG survey was very hot, with not good rainfall before the DCVG survey in the first quarter of 2044 and during the survey. Reference cell contact to earth resistance was good throughout the surveys, with additional watering. The right of ways consists of green grass areas of which the green grass areas retain surface moisture.

6.3 Direct Inspections

Analyses of indirect inspection data was performed to select sites for excavations and pipe surface evaluations. The data from the direct examinations are combined with prior data to assess the impact of external corrosion on the pipeline. Additional data including the evaluation of pipeline coating performance, corrosion defect repairs, and mitigation of corrosion protection faults are included in this step. As this is the first known ECDA assessment of the pipeline, additional data collection and direct examinations were completed to understand the pipeline integrity with respect to external soil side corrosion and other associated risks.

The direct inspections carried out were according to the indirect inspection summary report i.e., classified as immediate and/or scheduled. These areas were excavated and the comprehensive detail collected is dependent on a selected list of tests performed, on the as-found direct findings of which some of are listed below:

- ☐ Physical and visual assessment and record,
- ☐ Location, area, category and surrounding geography,
- ☐ As-found status and condition noting the type of soils, other utilities, CP and coating status, damage etc.,
- ☐ Coating condition, type, damage,
- ☐ CP status, direct measurements, calcareous deposits,
- ☐ Corrosion classification and metal loss and measure ,
- ☐ 3rd party mechanical damage, as-built, coating damage, metal loss etc.,
- ☐ Damage review and classification
- ☐ Non-Destructive Testing (NDT) where required included, pipe wall thickness and phased array.

7 ECDA Classification of Findings

7.1 Pre-Assessment (ECDA Region Identifications)

The pipeline is situated in a highly congested area, classified as a Class 3 zone, where stray current interference and presence of other utilities lines are present. From the data and pipeline records received to date, the pipeline is defined into 1 section:

- Section from the Phalaborwa WTW to the Phalaborwa Mining Company.

The section is classified into the same ECDA region for the indirect examination phase where predominantly the DCVG was used to identify coating anomalies.

Over the lengthy time history of the pipeline, some sections have been replaced and repaired. A leak along the section was also reported and attributed to external corrosion. There are no leak registry archives, however the records indicate that leaks had been repaired with emergency mechanical clamps. These repairs are classified as temporary repairs and this section of piping with the temporary clamp repairs will need to be replaced.

7.2 Pipe To Soil Potentials and ACVG Findings

Pipe to soil potentials measured were recorded and collected as negative potentials when compared to saturated copper sulphate reference electrode, and the value thereof is used as the corrosion criteria/predictor.

NACE RP0169-2002, stipulates the following protection criteria, which is the minimum criteria:

- (-850 rule) Potentials more negative than -850 millivolts would indicate adequate levels of CP protection to mitigate soil side corrosion in soils with no MIC.

As per NACE SP0502 guidelines, the analysis and classification of pipe to soil potential data, is the process of estimating the possibility of corrosion activity throughout the given year.

7.3 DCVG Coating Defect Classification

DCVG defect severity sizing is referenced as per NACE SP0502 and shown in Table 2, there are small, medium and large coating defects. Using the standard interpolation calculation, the percentage calculation estimates for the coating size are calculated. The sizing estimation is indicative and it should be noted here that the pipe depth, soil resistivity and any surface deposits on the metal surface at the coating defect will affect this calculation. Field verification findings are necessary to correlate and quantify these findings.

Table 2: Summary of DCVG classifications and findings

| No. | % IR Severity | Classification | Verification |
|-----|---------------|----------------|-----------------|
| 1 | 0-15% | Small | To be confirmed |
| 2 | 16-35% | Medium | To be confirmed |
| 3 | >36% | Large | To be confirmed |

7.4 Soil Resistivity Survey and Profile

A soil resistivity survey was carried out along the pipeline ROW at regular spaced intervals, to determine the degree of corrosivity of the soil. The technique used was the Wenner-4-pin method, as per specification ASTM G57. The relationship between resistivity and corrosivity as a guideline is given in Table 3 below.

Table 3: Relationship between resistivity and corrosivity

| Resistivity ($\Omega.m$) | Corrosivity |
|----------------------------|---------------------|
| <10 | Extremely Corrosive |
| 10 to 50 | Very Corrosive |
| 51 to 100 | Mildly Corrosive |
| > 100 | Non-Corrosive |

7.5 Direct Inspection Findings

For initial ECDA studies, a minimum of two direct examinations shall be performed. In the case where indications have been identified and classified, the following rulings apply for Direct Examinations, as summarized in Table 4:

Table 4: Summary of classifications and Direct Inspection Requirements

| Classification | Descriptive |
|-------------------------|--|
| Minor / To be Monitored | Not required if a scheduled/immediate area is examined. A minimum of 2 areas are to be examined if ECDA is applied for the first time. |
| Moderate / Scheduled | One area to be examined, pending on findings of pipeline operator can be More or Less conservative & inspect another area |
| Severe / Immediate | Requires direct examination |

A total of two sites were exposed for direct inspection and analysis. The findings of the direct inspection which include the detailed list of findings and visual records and magnitudes of metal loss are contained in Appendix 3.

8 Summary Of ECDA Indirect Survey Findings

8.1 Soil Resistivity Survey

The average soil resistivities at the depths specified, indicate that most of the pipeline route is in the non-corrosive area, however there are areas that gave extremely corrosive results. As few as they are, they can still contribute to a great deal of corrosion activity if other corrosion conditions are present, hence it would be advisable to consider soils as corrosive for the design purposes.

8.2 Summary Of DCVG Findings

Table 5 below, summarizes the DCVG findings. This includes the total number of defects, the cumulative distance surveyed and the defect severity and category ranking of the number of defects.

Table 5: Summary of the DCVG results

| Pipeline Section | Distance Surveyed (Km) | Total No. Defects | Defects Small | Defects Medium | Defects > Large |
|---------------------|------------------------|-------------------|---------------|----------------|-----------------|
| Entire 9Km Pipeline | 9 | 115 | 65 | 40 | 10 |

Table 6 present a summary of the severe/immediate and scheduled/moderate areas of concern, when looking at the results of indirect survey technique and taking into consideration the classifications and capabilities of the survey technique.

Table 6: Summary of the DCVG Severe/Immediate and Scheduled areas of Concern

| Pipeline Section | Reference TS | Run | Classification | Comment |
|---------------------|--------------|-----|----------------|----------------------------|
| Entire 9km Pipeline | D | 2 | Monitored | 2 coating defects located. |

8.3 ROW and Test Station Findings

There are vandalized test stations situated along the pipeline route. The test stations are classified as critical bond, bonding and/or monitoring test stations. Start and end potential readings were taken at the valves at the WTW and Chambers, concluding a 9000m survey. The detailed test station report is contained in Appendix 1. Other valve chambers were opened and visually inspected, most contained water surrounding the pipeline. External corrosion was visible in areas where the pipe was in-direct contact with the water, inside the valve chamber.



FIGURE 1 : WATER FLOODED VALVE CHAMBER.



FIGURE 2 : CP TEST POST

8.4 DCVG Results

The survey results and findings are presented in two test runs, starting at the Phalaborwa WTW and finishing at the Chamber. Most coating defects were located at the pipeline welding seams. The sizing classification indicates there are defects that require attention and the classification is given as immediate or scheduled either due to large gradients and/or sudden changes in the gradient potentials.

In general, the findings conclude that the external coating on the pipeline varies, some areas are showing good coating and other areas are showing bad coating. The defect distribution and relative severity is shown in Appendix 2, which shows a clustered distribution along certain sections along its route.

8.5 NDT Results

NDT tests measured a pipe wall thickness of 4.17mm to 6mm at Scan Excavation 1A and pipe wall thickness at Scan Excavation 1B indicating no wall loss noted as thickness ranges from 5.5mm.

The detailed findings of the NDT tests performed are contained in Appendix 3.

8.6 Direct Inspection Results

Potential measurements showed an On potential of -0.402V. Examination of the pipe surface showed a blast profiled pipe surface, with no areas of external metal loss or areas of mechanical damage, noted.

The external pipe coating in the second excavation was repaired and the surrounding area was backfilled and re-instated, in accordance with Lepelle Northern Water pipeline requirements and specifications, upon completion of the direct inspection tests.

8.7 Excavation 01

The surrounding soil consist of no sand padding or backfill around the pipe, red soil covers the pipe to grade level. The average grade cover to pipe top dead center measured 1.6m. The external coating is a bitumen wrap. Closer inspection of the pipe coating indicated a coating tear at the 04 o'clock position possibly attributed to 3rd party mechanical damage caused by sling/strap damage during handling of the pipeline during construction. Careful exposure of the pipe surface showed a thick build-up of calcareous deposits, the removal hereof showed a corrosion pit feature that showed the presence of magnetite.

8.8 Excavation 02

The surrounding soils consist of no sand padding or backfill around the pipe, red soil covers the pipe to grade level. The average grade cover to pipe top dead centre measured 1.6 m. Closer inspection of the pipe coating found two coating anomalies on the pipe bend, possibly attributed due to the tight bend radius.

No visible metal loss was found on removal of the coating. NDT tests measured a pipe wall thickness of 5.5mm along this section and were reported as acceptable.

9 Conclusion

9.1 In-Line Inspection (ILI) CCTV Survey Conclusion

The following findings were obtained from the CCTV in-line inspection;

- ☐ Sections of the pipe lining have undergone blistering , cracking and peeling.
- ☐ Rust spotting and rust staining was observed.
- ☐ The internal lining system is deteriorating due to the pipeline age.

9.2 External Corrosion Direct Assessment (ECDA) Survey Conclusion

The results found from employing the ECDA techniques gave the following findings:

- ☐ The health or integrity of the pipeline is of paramount importance, owing to its geographic area that is built up and sharing its servitude with other pipelines from Lepelle Northern Water and those of other third parties.
- ☐ The pipeline was found to be crossing high voltage power line servitudes , which is a cause for concern when it comes to stray currents jumping into the pipeline , it is highly likely that when those currents leave the pipeline , that is where corrosion is likely to occur.
- ☐ The corrosivity of the soil in the area was found to be mostly non-corrosive with an exception of a few areas which gave a negative spike and reported corrosivity. The few corrosive areas are capable of causing a great deal of destruction when other negative factors are present on those areas.
- ☐ The presence of corrosion pits indicates the active metal loss took place early in the pipeline's life as the coating damage suggests 3rd party mechanical handling (slings/strap) damage.
- ☐ The cathodic protection system was installed and commissioned, but due to theft and vandalism , the pipeline has not been protected for years.
- ☐ The wall thickness results suggested that the pipe has not experienced substantial metal loss, but the issues were found to be on the previously repaired areas and areas where temporary clamps are installed.
- ☐ The wall thickness loss was experienced mainly on pipe joints, and that is where corrosion is more likely to attack, with the historic data showing that more bursts and leaks have been reported to have been found mostly on the pipe joints.

9.3 Overall Conclusion

After combining both in-line inspection and ECDA techniques, it is possible to conclude that the majority of pipeline failures can be traced back to repair methodologies in which the external coating was not restored or reinstated where it had been removed to carry out repairs, or in areas where temporary clamps were introduced. The pipeline is left bare and prone to external corrosion. The inside pipe lining was discovered to have deteriorated over time due to the age of the pipeline, but no conclusive evidence was found to show that the loss of internal lining led to bursts or structural failure of the pipe. The results of the wall thickness test, which indicated that the pipe has not lost thickness because it is still above 5mm for the majority of the pipeline from the 6mm thickness when it was laid, provide weight to this conclusion. The pipe joints were discovered to have lost the greatest amount of wall thickness, and the external coating was not in the best of shape.





10 Recommendations

The areas that require attention are summarised as follows:

- ☐ Repairs and upkeep of the cathodic protection system, to protect the pipeline from external corrosion.
- ☐ Cathodic protection, AC mitigation assessments and designs are recommended to protect the pipe from the 3rd party infrastructure such as Eskom HV lines that traverses the pipeline servitude.
- ☐ The corrosion of pipe sections within valve chambers can be reduced by an above-ground coating application, especially in areas where chambers experience a lot of water ingress.
- ☐ Exposure of all pipe joints, to assess and remedy where the welding and coating are found to be compromised, in order to prevent more bursts from occurring since the historical data shows that most bursts were located on pipe joints.
- ☐ A leak detection testing is still recommended after all the known defects have been addressed, when the pipe has been recommissioned to further ensure that all compromised areas are repaired.
- ☐ The pipeline's inner lining repairs are not a priority at this time because the lining failure cannot be traced back to the frequent pipe bursts or have a detrimental impact on the pipeline's structural integrity. The inner coating/lining repair methods were investigated, and it was discovered that because the pipe diameter was too smaller for humans to perform tasks safely within the pipe, other trenchless technologies were discovered and are appended to this report for informational purposes.

11 Appendices

11.1 Appendix 1 : CP Assets and Valve Chambers

| | | | | |
|---|--------------------------------|---|---|--|
| LEPELLE WATER / Coasttech Projects (Pty) Ltd. Conditional Assessment | | Visual Inspection Record AREA: WTW PHALABORWA TO PMC WTW Connection to PMC Pipeline | | |
| Project Number : | | Client : LEPELLE | Consultant : Coasttech Projects (Pty) Ltd | |
| Item | Description | Comments | | |
| 1 | Railway Line | NO AC Raiway Line crosses pipeline. | | |
| 2 | HVAC Powerline | HVAC Power lines, parallel to pipeline. | | |
| 3 | Foreign Pipeline | Lepelle Water pipelines running parallel.. | | |
| 4 | Test Post (Big Headed) | Vandalised Big Headed Type present,with nothing inside, no access to TP | | |
| 5 | Test Post (Monitoring) | No Monitoring Type Test Posts visible. | | |
| 6 | CP Bunker | No bunker present. | | |
| 7 | TRU plus Enclosure Type | No Durasafe TRU enclosure, no TRU or cables present. | | |
| 8 | NDU/FDU plus Enclosure Type | None observed. | | |
| 9 | ACM Bunker / SSDCD Device | None observed. | | |
| 10 | ACM Equipotential Gradient Mat | None observed. | | |
| 11 | Pipe Diameter | Approximately 9000m, pipe diameters 560mm. | | |
| 12 | Pipeline Coating | To be confirmed - Bitumen | | |
| 13 | Valve Chamber / Type | Concrete chambers, concrete lids, some vandalised. | | |
| 14 | Reservoir | None observed. | | |
| 16 | Leaks | leaks observed. | | |
| | | Photo Gallery | | |
|  | |  | | |
|  | |  | | |
| | | | | |
| | | SHEET 1 OF 2 | | |

| | | |
|---|---|--|
| <p>LEPELLE WATER / Coasttech Projects (Pty) Ltd. Conditional Assessment</p> | <p>Visual Inspection Record AREA: WTW PHALABORWA to PMC WTW Connection to PMC Pipeline</p> | |
|---|---|--|

| | | |
|-------------------------|-------------------------------|--|
| <p>Project Number :</p> | <p>Client : Lepelle Water</p> | <p>Consultant : Coasttech Projects (Pty) Ltd</p> |
|-------------------------|-------------------------------|--|

PHOTO GALLERY



11.2 Appendix 2 : ECDA Surveys CP Results

| LATITUDE | LONGITUDE | COMMENT | CHAINAGE | OLRE | SIGNAL START | SIGNAL END | %IR |
|---------------------------------------|-----------|--------------------|----------|------|--------------|------------|---------------------------|
| DCVG LEPELLE WATER WTW 560mm PIPELINE | | | | | | | |
| | | CHAMBER | 0 | 700 | 3215 | 2743 | |
| | | D1 | 24 | 500 | | | <div><div></div></div> 22 |
| | | D2 | 72 | 347 | | | <div><div></div></div> 16 |
| | | D4 | 90 | 777 | | | <div><div></div></div> 11 |
| | | D5, CHAMBER | 247.5 | 298 | | | <div><div></div></div> 25 |
| | | MP | 500 | | | | |
| | | D6 | 569.8 | 666 | | | |
| | | D7 | 682.3 | 877 | | | <div><div></div></div> 22 |
| | | D8 MP | 776.6 | 185 | | | <div><div></div></div> 29 |
| | | D9 | 803.2 | 309 | | | <div><div></div></div> 6 |
| | | D10, SV3 | 847 | 412 | | | <div><div></div></div> 10 |
| | | D11 | 0.1 | 327 | | | <div><div></div></div> 13 |
| | | D12 | 946 | 248 | | | <div><div></div></div> 11 |
| | | D13 | 1136 | 523 | | | <div><div></div></div> 9 |
| | | D14 | 1178.5 | 266 | | | <div><div></div></div> 18 |
| | | D15 | 1223 | 525 | | | <div><div></div></div> 9 |
| | | D16 | 1267.2 | 678 | | | <div><div></div></div> 19 |
| | | D17 | 1304 | 349 | | | <div><div></div></div> 24 |
| | | D18 | 1385.2 | 445 | | | <div><div></div></div> 13 |
| | | D19 | 1401.5 | 325 | | | <div><div></div></div> 16 |
| | | CHAMBER, TEST POST | 1520 | | 1427 | 1610 | |
| | | | | | | | |
| | | D20 | 1592 | 554 | | | <div><div></div></div> 37 |
| | | D21 | 1622.4 | 39 | | | <div><div></div></div> 3 |
| | | D22 | 1655.3 | 239 | | | <div><div></div></div> 16 |
| | | D23 | 1712.2 | 109 | | | <div><div></div></div> 7 |
| | | D24 | 1729.6 | 99 | | | <div><div></div></div> 7 |
| | | D25 | 1751.8 | 445 | | | <div><div></div></div> 30 |
| | | D26 | 1777.9 | 284 | | | <div><div></div></div> 19 |
| | | D27 | 1899.5 | 423 | | | <div><div></div></div> 28 |
| | | D28 | 2019 | 302 | | | <div><div></div></div> 20 |
| | | D29 | 2210.7 | 266 | | | <div><div></div></div> 18 |
| | | D30 | 2228.4 | 169 | | | <div><div></div></div> 11 |
| | | D31 | 2271.7 | 1101 | | | <div><div></div></div> 73 |
| | | D32 | 2993.6 | 674 | | | <div><div></div></div> 44 |
| | | D33 | 329 | 346 | | | <div><div></div></div> 24 |
| | | D34 | 3531.5 | 877 | | | <div><div></div></div> 56 |
| | | D35 | 3681.7 | 1173 | | | <div><div></div></div> 75 |
| | | D36 | 3772.4 | 1400 | | | <div><div></div></div> 89 |
| | | D37 | 3792.8 | 1082 | | | <div><div></div></div> 69 |
| | | D38 | 3823.2 | 299 | | | <div><div></div></div> 19 |
| | | D39 | 3478.5 | 446 | | | <div><div></div></div> 29 |
| | | D40 | 3485.8 | 278 | | | <div><div></div></div> 18 |
| | | D41 | 3594.9 | 427 | | | <div><div></div></div> 27 |
| | | D42 | 3703.4 | 882 | | | <div><div></div></div> 56 |
| | | CHAMBER | 3994 | | | | |
| | | | | | | | |
| | | D43 | 4000 | 266 | | | <div><div></div></div> 17 |
| | | D44 SV | 4123.5 | 385 | | | <div><div></div></div> 24 |
| | | D45 | 4229.5 | 226 | | | <div><div></div></div> 14 |
| | | D46 | 4277.6 | 229 | | | <div><div></div></div> 14 |
| | | D47 | 4298.2 | 339 | | | <div><div></div></div> 21 |
| | | D48 | 4303.5 | 189 | | | <div><div></div></div> 12 |
| | | D49 | 4325.5 | 279 | | | <div><div></div></div> 18 |
| | | D50 | 4351.5 | 378 | | | <div><div></div></div> 24 |
| | | D51 SV | 4376.5 | 328 | | | <div><div></div></div> 21 |
| | | D52 | 4397.9 | 340 | | | <div><div></div></div> 21 |
| | | D53 | 4436.6 | 326 | | | <div><div></div></div> 20 |
| | | D54 | 4455.6 | 230 | | | <div><div></div></div> 14 |
| | | D55 | 4476.7 | 195 | | | <div><div></div></div> 12 |
| | | D56 | 4495.3 | 330 | | | <div><div></div></div> 21 |
| | | D57 | 4513.2 | 386 | | | <div><div></div></div> 24 |
| | | D58 | 4524.7 | 435 | | | <div><div></div></div> 27 |
| | | D59 | 4548.7 | 314 | | | <div><div></div></div> 20 |
| | | D60 | 4560.3 | 117 | | | <div><div></div></div> 7 |
| | | D61 | 4572.7 | 148 | | | <div><div></div></div> 9 |
| | | D62 | 4584.7 | 190 | | | <div><div></div></div> 12 |
| | | CHAMBER | 4786.9 | | 3993 | 1926 | |
| | | | | | | | |
| | | D63 | 4793.6 | 387 | | | <div><div></div></div> 18 |
| | | D64 | 4821.2 | 298 | | | <div><div></div></div> 14 |

| | | | | | | | |
|--|--|----------------------|--------|------|------|------|---------------------------|
| | | D65 | 4843.4 | 87 | | | <div><div></div></div> 4 |
| | | D66 | 4960.4 | 56 | | | <div><div></div></div> 3 |
| | | D67 | 4991.9 | 128 | | | <div><div></div></div> 6 |
| | | D68 | 5023.1 | 272 | | | <div><div></div></div> 13 |
| | | D69 | 5059.4 | 78 | | | <div><div></div></div> 4 |
| | | D70 | 5109.8 | 166 | | | <div><div></div></div> 8 |
| | | D71 | 5224.2 | 150 | | | <div><div></div></div> 7 |
| | | D72 | 5237.6 | 211 | | | <div><div></div></div> 11 |
| | | D73 | 5346.7 | 268 | | | <div><div></div></div> 14 |
| | | D74 | 5374.9 | 275 | | | <div><div></div></div> 14 |
| | | D75 | 5395.1 | 127 | | | <div><div></div></div> 7 |
| | | D76 | 5399 | 79 | | | <div><div></div></div> 4 |
| | | D77 | 5400.7 | 132 | | | <div><div></div></div> 7 |
| | | D78 | 5407.2 | 237 | | | <div><div></div></div> 12 |
| | | D79 | 5412.4 | 300 | | | <div><div></div></div> 16 |
| | | CHAMBER AV | 5419 | | 3282 | 2822 | |
| | | | | | | | |
| | | D80 | 5517.4 | 497 | | | <div><div></div></div> 17 |
| | | D81 | 5545.6 | 219 | | | <div><div></div></div> 7 |
| | | D82 | 5588.7 | 27 | | | <div><div></div></div> 1 |
| | | D83 | 6104.7 | 24 | | | <div><div></div></div> 1 |
| | | D84 | 6136.2 | 98 | | | <div><div></div></div> 3 |
| | | D85 | 6163.7 | 88 | | | <div><div></div></div> 3 |
| | | D86 | 6174.8 | 202 | | | <div><div></div></div> 7 |
| | | D87 | 6193.7 | 106 | | | <div><div></div></div> 4 |
| | | D88 | 6205.8 | 45 | | | <div><div></div></div> 2 |
| | | D89 | 6216.7 | 53 | | | <div><div></div></div> 2 |
| | | D90 | 6236.5 | 68 | | | <div><div></div></div> 2 |
| | | D91 | 6277.2 | 394 | | | <div><div></div></div> 14 |
| | | D92 | 6290.3 | 230 | | | <div><div></div></div> 8 |
| | | D93 | 6303.1 | 331 | | | <div><div></div></div> 11 |
| | | D94 | 6371.1 | 356 | | | <div><div></div></div> 12 |
| | | D95 | 6454.2 | 486 | | | <div><div></div></div> 17 |
| | | D96 | 6566.2 | 166 | | | <div><div></div></div> 6 |
| | | D97 | 6687.2 | 34 | | | <div><div></div></div> 1 |
| | | D98 | 6995 | 1800 | | | <div><div></div></div> 63 |
| | | PIPE EXPOSED | 7000 | | | | <div><div></div></div> 0 |
| | | | | | | | |
| | | CENTRE STREAM | 7333 | | | | |
| | | D99 | 7350.1 | 204 | | | <div><div></div></div> 7 |
| | | D100 | 7369.4 | 343 | | | <div><div></div></div> 12 |
| | | D101 | 7372.6 | 129 | | | <div><div></div></div> 5 |
| | | VANDALIZED TEST POST | 7416 | | 4977 | 1570 | |
| | | | | | | | |
| | | D102 | 7510.1 | 67 | | | <div><div></div></div> 2 |
| | | D103 | 7644.8 | 233 | | | <div><div></div></div> 7 |
| | | D104 | 7761.1 | 344 | | | <div><div></div></div> 10 |
| | | D105 | 7873.9 | 358 | | | <div><div></div></div> 11 |
| | | D106 SV | 7889.2 | 277 | | | <div><div></div></div> 8 |
| | | D107 | 7916.8 | 138 | | | <div><div></div></div> 4 |
| | | D108 | 7928.1 | 98 | | | <div><div></div></div> 3 |
| | | VANDALIZED TP | 7937 | | 2668 | 2300 | |
| | | | | | | | |
| | | D109 | 8193.2 | 322 | | | <div><div></div></div> 14 |
| | | D110 | 8227.7 | 182 | | | <div><div></div></div> 8 |
| | | D111 | 8551.4 | 85 | | | <div><div></div></div> 4 |
| | | D112 | 8669 | 765 | | | <div><div></div></div> 33 |
| | | D113 | 8776.1 | 58 | | | <div><div></div></div> 3 |
| | | D114 | 8882.2 | 336 | | | <div><div></div></div> 15 |
| | | D115 SV | 8942 | 583 | | | <div><div></div></div> 25 |
| | | CHAMBER | 9000 | | 1298 | 250 | |

| Survey date: | Phalaborwa | Measured from WTW of Chamber On Lepelle | Bulk Resistance Ohm 1.6m Pin Spacing | Bulk Soil Resistivity Ohm-m 1.6m Depth | |
|--------------|-------------|--|---|--|--------------|
| DD.ddddddd | DD.ddddddd | | | | |
| H_Latitude | H_Longitude | Distance(m) | Res | Res | Comments |
| -24.065067 | 31.1415 | 0 | 24 | 241.37 | Survey Start |
| -24.064205 | 31.141237 | 100 | 12 | 120.69 | |
| -24.063347 | 31.140995 | 200 | 32 | 321.83 | |
| -24.062515 | 31.14077 | 300 | 29 | 291.66 | |
| -24.061663 | 31.140502 | 400 | 24 | 241.37 | |
| -24.06085 | 31.140247 | 500 | 21 | 211.20 | |
| -24.059987 | 31.139993 | 600 | 18 | 181.03 | |
| -24.059153 | 31.139752 | 700 | 31 | 311.77 | |
| -24.058312 | 31.139502 | 800 | 17 | 170.97 | |
| -24.057495 | 31.139252 | 900 | 13 | 130.74 | |
| -24.056647 | 31.139035 | 1000 | 37 | 372.11 | |
| -24.055773 | 31.138773 | 1100 | 21 | 211.20 | |
| -24.054945 | 31.13849 | 1200 | 36 | 362.06 | |
| -24.054945 | 31.13849 | 1300 | 19 | 191.09 | |
| -24.0533 | 31.13797 | 1400 | 20 | 201.14 | |
| -24.05244 | 31.137743 | 1500 | 27 | 271.54 | |
| -24.0516 | 31.13749 | 1600 | 22 | 221.26 | |
| -24.050782 | 31.137428 | 1700 | 26 | 261.49 | |
| -24.049935 | 31.136903 | 1800 | 30 | 301.71 | |
| -24.049003 | 31.136787 | 1900 | 109 | 1096.23 | |
| -24.048283 | 31.136587 | 2000 | 36 | 362.06 | |
| -24.047435 | 31.136227 | 2100 | 51 | 512.91 | |
| -24.046617 | 31.135983 | 2200 | 30 | 301.71 | |
| -24.045787 | 31.135783 | 2300 | 11 | 110.63 | |
| -24.04508 | 31.135508 | 2400 | 36 | 362.06 | |
| -24.044098 | 31.13527 | 2500 | 64 | 643.66 | |
| -24.043402 | 31.135045 | 2600 | 27 | 271.54 | |
| -24.042432 | 31.134772 | 2700 | 24 | 241.37 | |
| -24.041593 | 31.134467 | 2800 | 27 | 271.54 | |
| -24.040752 | 31.134243 | 2900 | 27 | 271.54 | |
| -24.03984 | 31.134088 | 3000 | 6 | 60.34 | |
| -24.038978 | 31.133798 | 3100 | 15 | 150.86 | |
| | | 3200 | | | River Start |
| | | 3300 | | | River End |
| -24.03641 | 31.133037 | 3400 | 18 | 181.03 | |

| | | | | | |
|-------------|-----------|------|-----|---------|---|
| -24.035572 | 31.132743 | 3500 | 16 | 160.91 | |
| -24.034728 | 31.132503 | 3600 | 75 | 754.29 | |
| -24.033895 | 31.132275 | 3700 | 35 | 352.00 | |
| -24.033038 | 31.132025 | 3800 | 21 | 211.20 | |
| -24.032135 | 31.13173 | 3900 | 44 | 442.51 | |
| -24.031302 | 31.131495 | 4000 | 43 | 432.46 | |
| -24.030433 | 31.13123 | 4100 | 45 | 452.57 | |
| -24.029548 | 31.130978 | 4200 | 44 | 442.51 | |
| -24.028733 | 31.130705 | 4300 | 70 | 704.00 | |
| -24.027853 | 31.130495 | 4400 | 28 | 281.60 | |
| -24.027087 | 31.130347 | 4500 | 102 | 291.66 | 3 HV Eskom Powerlines running parallel with the pipelines |
| -24.026628 | 31.131182 | 4600 | 31 | 311.77 | |
| -24.026052 | 31.131838 | 4700 | 30 | 301.71 | |
| -24.025515 | 31.132603 | 4800 | 30 | 301.71 | |
| -24.024988 | 31.133348 | 4900 | 29 | 291.66 | |
| -24.024462 | 31.134128 | 5000 | 32 | 321.83 | |
| -24.023945 | 31.134942 | 5100 | 14 | 140.80 | |
| -24.02347 | 31.135547 | 5200 | 23 | 231.31 | |
| -24.02288 | 31.136407 | 5300 | 28 | 281.60 | |
| -24.022375 | 31.137203 | 5400 | 27 | 271.54 | |
| -24.021893 | 31.13788 | 5500 | 25 | 251.43 | |
| -24.021247 | 31.138863 | 5600 | 32 | 321.83 | |
| -24.020823 | 31.139488 | 5700 | 48 | 482.74 | |
| -24.020243 | 31.140172 | 5800 | 24 | 241.37 | |
| -24.01948 | 31.140575 | 5900 | 33 | 331.89 | |
| -24.018738 | 31.14114 | 6000 | 3 | 30.17 | |
| -24.018095 | 31.141708 | 6100 | 57 | 573.26 | |
| -24.017373 | 31.142138 | 6200 | 189 | 1900.80 | |
| -24.016538 | 31.142598 | 6300 | 130 | 1307.43 | |
| -24.015743 | 31.142972 | 6400 | 140 | 1408.00 | |
| -24.015093 | 31.14326 | 6500 | 42 | 422.40 | |
| 4.014097 | 31.14377 | 6600 | 41 | 412.34 | |
| -24.013423 | 31.144098 | 6700 | 33 | 331.89 | |
| -24.012575 | 31.144442 | 6800 | 43 | 432.46 | |
| -24.011815 | 31.14485 | 6900 | 44 | 442.51 | |
| -24.011003 | 31.145227 | 7000 | 43 | 432.46 | |
| -24.010203 | 31.145447 | 7100 | 4 | 40.23 | |
| -24.009393 | 31.145733 | 7200 | 32 | 321.83 | |
| -24.008468 | 31.145913 | 7300 | 1.3 | 13.07 | |
| -24.007598, | 31.146218 | 7400 | 10 | 100.57 | |
| -24.006895 | 31.146403 | 7500 | 21 | 211.20 | |

| | | | | | |
|------------|-----------|------|-----|---------|-------------|
| -24.00599 | 31.146655 | 7600 | 29 | 291.66 | |
| -24.00506 | 31.146918 | 7700 | 13 | 130.74 | |
| -24.00421 | 31.147237 | 7800 | 18 | 181.03 | |
| -24.003345 | 31.147505 | 7900 | 4.2 | 42.24 | |
| | | 8000 | 1.2 | 12.07 | |
| | | 8100 | 6 | 60.34 | |
| -24.000818 | 31.148307 | 8200 | 21 | 211.20 | |
| -23.99998 | 31.14826 | 8300 | 5 | 50.29 | |
| -23.999237 | 31.147772 | 8400 | 0.9 | 9.05 | Proposed GB |
| -23.998462 | 31.147412 | 8500 | 16 | 160.91 | |
| -23.997628 | 31.147107 | 8600 | 39 | 392.23 | |
| -23.996872 | 31.146598 | 8700 | 161 | 1619.20 | |
| -23.996035 | 31.146193 | 8800 | 54 | 543.09 | |
| -23.99545 | 31.145788 | 8900 | 51 | 512.91 | |
| -23.994467 | 31.145272 | 9000 | 9 | 90.51 | Survey End |

11.3 Appendix 3 : Metal Loss Assessment Results






Phased Array Ultrasonic Examination Report





| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 1 of 9 |



Heat Treatment &
NDE Services (PTY) Ltd



| | | | | | | | | | | | |
|----------------|----------------|---|---------------|----------------|---|----------|----------------|---|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LII | | Qualification: | PCN LII | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: |  | | Signature: |  | | Signature: |  | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |


| | | | | | | | | | | | |
|--|---|--|------------------------|--------------------|---|------------------|----------------|---|--------|----------------|--|
|  | <h1 style="text-align: center;">Phased Array Ultrasonic Examination Report</h1> | | | | | Report No.: | SEC2-PAUT-0135 | | | | |
| | | | | | | Job No.: | Not Applicable | | | | |
| | | | | | | Equipment No.: | Water Pipe | | | | |
| | | | | | | Page No.: | 2 of 9 | | | | |
| CONTRACT DETAIL | | | | | | | | | | | |
| Date of Test: | 05 March 2024 | Material: | Carbon Steel | Spec. Criteria: | ASME V Art 4 2021 | | | | | | |
| Client: | Lepelle NW | Surface Condition: | As Cleaned | Acc. Criteria: | Record & Report | | | | | | |
| Location: | PMC | Weld Process: | Not Applicable | Work Procedure: | WP 023 Rev 0 | | | | | | |
| Description: | See Remarks | Diameter/Thickness: | 560NB | Work Instruction: | See Scan Plan | | | | | | |
| Drawing / QCP No.: | Not Applicable | PWHT: | Before - After - N/A X | Calibration Sheet: | WR-06-03-2024_PAUT | | | | | | |
| EQUIPMENT DETAIL | | | | | | | | | | | |
| Equipment Type: | Omniscan X3 | Wedge Specification: | REX 1 | Coll. Hardware : | MXU - 5.14,1 | | | | | | |
| Equipment I.D.: | 85421 | Wedge I.D.: | REX 1 | Cal. Block(s) : | IIW V1 | | | | | | |
| Probe Specification: | 7.5DL32 32X5--REX1 | Scanner Type: | Scanbuddy | Reference Block: | - | | | | | | |
| Probe I.D.: | V0612 | Scanner I.D.: | NJM 1 | Cal. Block Temp.: | - | | | | | | |
| Temp. Meter Type: | - | Temp. Meter Ser. No.: | - | Material Temp.: | - | | | | | | |
| CALIBRATION DETAIL | | | | | | | | | | | |
| TCG/DAC | X | AVG | | SDH | 2,5mm | FBH | | NOTCH | | % FSH | |
| Setup Information | | Scan Type | | 1st Element | | Element Quantity | | Last Element | | Wave Type | |
| GRP 1 | | Linear | | 1 | | 32 | | 32 | | SW | |
| - | | - | | - | | - | | - | | - | |
| - | | - | | - | | - | | - | | - | |
| - | | - | | - | | - | | - | | - | |
| - | | - | | - | | - | | - | | - | |
| Limitations: | | Restricted Access due to close proximity of pipe. On Excavation 1 (Start) Clampand patch restricted access. See P4 | | | | | | | | | |
| Remarks: | | PAUT Corrosion mapping was done on 2 excavated areas | | | | | | | | | |
| Results: | | See page 4 to 9. | | | | | | | | | |
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LH | | Qualification: | PCN LH | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: |  | | Signature: |  | | Signature: |  | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |



Phased Array Ultrasonic Examination Report

| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 3 of 9 |

Scan Plan




| | | | | | | | | | | | |
|----------------|----------------|------------|---------------|----------------|------------|----------|----------------|---------------|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LII | | Qualification: | PCN LII | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: | | | Signature: | | | Signature: | | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |




Phased Array Ultrasonic Examination Report

| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 4 of 9 |

Excavation 1 (Start)




| | | | | | | | | | | | |
|----------------|----------------|---|---------------|----------------|--|----------|----------------|---|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LII | | Qualification: | PCN LII | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: |  | | Signature: |  | | Signature: |  | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |



Phased Array Ultrasonic Examination Report

| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 5 of 9 |

Scan Excavation 1A




| | | | | | | | | | | | |
|----------------|----------------|------------|---------------|----------------|------------|----------|----------------|---------------|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LII | | Qualification: | PCN LII | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: | | | Signature: | | | Signature: | | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |






Phased Array Ultrasonic Examination Report

| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 6 of 9 |

Excavation 1 (Start)




| | | | | | | | | | | | |
|----------------|----------------|---|---------------|----------------|--|----------|----------------|---|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LII | | Qualification: | PCN LII | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: |  | | Signature: |  | | Signature: |  | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |



Phased Array Ultrasonic Examination Report

| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 7 of 9 |

Scan Excavation 1B



| | | | | | | | | | | | |
|----------------|----------------|------------|---------------|----------------|------------|----------|----------------|---------------|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LII | | Qualification: | PCN LII | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: | | | Signature: | | | Signature: | | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |



Phased Array Ultrasonic Examination Report

| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 8 of 9 |

Excavation 2 (End)




| | | | | | | | | | | | |
|----------------|----------------|------------|---------------|----------------|------------|----------|----------------|---------------|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LII | | Qualification: | PCN LII | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: | | | Signature: | | | Signature: | | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |



Phased Array Ultrasonic Examination Report

| | |
|----------------|----------------|
| Report No.: | SEC2-PAUT-0135 |
| Job No.: | Not Applicable |
| Equipment No.: | Water Pipe |
| Page No.: | 9 of 9 |

Scan Excavation 2



| | | | | | | | | | | | |
|----------------|----------------|------------|---------------|----------------|------------|----------|----------------|---------------|--------|----------------|--|
| Data Collector | Name: | WR Venter | Data Analyzer | Name: | WR Venter | Reviewer | Name: | GP le Roux | Client | Name: | |
| | Qualification: | PCN LI | | Qualification: | PCN LI | | Qualification: | SNT TC 1A LII | | Qualification: | |
| | Signature: | | | Signature: | | | Signature: | | | Signature: | |
| | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | 2024/03/06 | | Date: | |

11.4 Appendix 4 : CCTV Survey Results

Inspection Report CCTV

Survey reference – Condition Assesment on 9,5KM Pipeline at Phalaborwa WTW

Date – 290823

Contents

- Drain / Sewer Survey..... 4**
 - 1.1 Survey Header 4
 - 1.2 Diagram..... 5
 - 1.3 Observations 6
 - 1.4 Photographs 8
 - 1.5 Inclination Graph..... 10
- 2 Drain / Sewer Survey..... 11**
 - 2.1 Survey Header 11
 - 2.2 Diagram..... 12
 - 2.3 Observations 13
 - 2.4 Photographs 16
 - 2.5 Inclination graph 18
- 3 Drain / Sewer Survey..... 19**
 - 3.1 Survey Header 19
 - 3.2 Diagram..... 20
 - 3.3 Observations 21
 - 3.4 Photographs 23
 - 3.5 Inclination graph 25
- 4 Drain / Sewer Survey..... 26**
 - 4.1 Survey Header 26
 - 4.2 Diagram..... 27
 - 4.3 Observations 28
 - 4.4 Photographs 29
 - 4.5 Inclination graph 30
- 5 Drain / Sewer Survey..... 31**
 - 5.1 Survey Header 31
 - 5.2 Diagram..... 32
 - 5.3 Observations 33


| | | |
|----------|----------------------------------|-----------|
| 5.4 | Photographs | 34 |
| 5.5 | Inclination Graph..... | 35 |
| 6 | Drain / Sewer Survey..... | 36 |
| 6.1 | Survey Header | 36 |
| 6.2 | Diagram..... | 37 |
| 6.3 | Observations | 38 |
| 6.4 | Photographs | 39 |
| 6.5 | Inclination graph | 40 |

Drain / Sewer Survey






1.1 Survey Header





| | | |
|--------|---------------------------|--|
| 1.1.1 | Surveyed by (Operator) | AKANI/DARREN |
| 1.1.2 | Contract no. | |
| 1.1.3 | Job no. | |
| 1.1.4 | Catchment (Drainage area) | |
| 1.1.5 | Division | LEPELLE NORTHERN WATER |
| 1.1.6 | District | MOPANE |
| 1.1.7 | Pipeline length ref | 9500 |
| 1.1.8 | Date | 290823 |
| 1.1.9 | Time | 10:25 |
| 1.1.10 | Location | PHALABORWA |
| 1.1.11 | Start manhole no. | CHAMBER1(AIR VALVE) |
| 1.1.12 | Start depth | |
| 1.1.13 | Start cover level | |
| 1.1.14 | Start invert level | 2.64 |
| 1.1.15 | Finish manhole no. | AIR VALVE |
| 1.1.16 | Finish depth | |
| 1.1.17 | Finish cover level | |
| 1.1.18 | Finish invert level | 2.74 |
| 1.1.19 | Use of Drain | (Z) Not Known |
| 1.1.20 | Direction | (U) Survey upstream (camera pointing against flow) |
| 1.1.21 | Size 1 (diameter/height) | 560mm |
| 1.1.22 | Size 2 (width) | |
| 1.1.23 | Shape | (C) Circular |
| 1.1.24 | Material | (ST) Steel |
| 1.1.25 | Lining | |
| 1.1.26 | Pipe length | 150m |
| 1.1.27 | Total length | 9500m |
| 1.1.28 | Year laid | N/A |
| 1.1.29 | Video cassette number | |
| 1.1.30 | Comments: General | |
| 1.1.31 | Purpose | (Z) Not Known |
| 1.1.32 | Sewer category | (Z) Not Known |
| 1.1.33 | Pre-cleaning | (N) No |
| 1.1.34 | Weather | |
| 1.1.35 | Location code | |
| 1.1.36 | Further location details | |

1.2 Diagram



1.3 Observations

| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|---|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 8.2 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-10_42_122.jpg 2023-08-29 10:40:42 8.18m -6.5°  |
| | PIPE | 0:00:46 |
| 49.7 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-10_44_00_498.jpg 2023-08-29 10:44:00 49.68m -5.4°  |
| | PIPE | 0:03:51 |
| 53.7 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-10_44_46_545.jpg 2023-08-29 10:44:46 53.73m -5.9°  |
| | PIPE | 0:04:21 |
| 86.2 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-10_49_10_302.jpg 2023-08-29 10:49:10 86.24m -5.5°  |
| | PIPE | 0:06:58 |
| 120.6 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-10_51_55_415.jpg 2023-08-29 10:51:55 120.63m -5.2°  |
| | PIPE CONDITION | 0:09:34 |

| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|---|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 152.3 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-10_55_18_712.jpg 2023-08-29 10:55:18 152.26m -3.7°  |
| | | |
| | | |
| | PIPE CONDITION | 0:12:43 |
| 167.8 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-10_58_45_408.jpg 2023-08-29 10:58:45 167.77m -0.2°  |
| | | |
| | | |
| | PIPE CONDITION | 0:14:41 |
| 194.6 | (GO) General observation at this point | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-11_02_16_911.jpg 2023-08-29 11:02:16 194.64m -0.3°  |
| | | |
| | | |
| | PIPE CONDITION | 0:17:57 |
| 240.3 | (SA) Survey abandoned | ./2023-08-29-10-25-26/2023-08-29-10-25-26_2023_08_29-11_09_47_473.jpg 2023-08-29 11:09:47 240.27m 0.4°  |
| | | |
| | | |
| | CRAWLER STUCK DUE TO PIPE JOINT | 0:25:15 |

1.4 Photographs


(GO) General observation at this point ./2023-08-29-10-25-26/2023-08-29-10-25-22.jpg (GO) General observation at this point ./2023-08-29-10-25-26/2023-08-29-10-25-98.jpg




(GO) General observation at this point ./2023-08-29-10-25-26/2023-08-29-10-25-5.jpg (GO) General observation at this point ./2023-08-29-10-25-26/2023-08-29-10-25-02.jpg




(GO) General observation at this point ./2023-08-29-10-25-26/2023-08-29-10-25-5.jpg (GO) General observation at this point ./2023-08-29-10-25-26/2023-08-29-10-25-12.jpg




(GO) General observation at this point
./2023-08-29-10-25-26/2023-08-29-10-25-26.jpg




(GO) General observation at this point
./2023-08-29-10-25-26/2023-08-29-10-25-26-1.jpg



(SA) Survey abandoned
./2023-08-29-10-25-26/2023-08-29-10-25-26-2.jpg



1.5 Inclination Graph




2 Drain / Sewer Survey

2.1 Survey Header






| | | |
|--------|---------------------------|---|
| 2.1.1 | Surveyed by (Operator) | AKANI/DARREN |
| 2.1.2 | Contract no. | |
| 2.1.3 | Job no. | |
| 2.1.4 | Catchment (Drainage area) | |
| 2.1.5 | Division | LEPELLE NORTHERN WATER |
| 2.1.6 | District | MOPANE |
| 2.1.7 | Pipeline length ref | 9500 |
| 2.1.8 | Date | 290823 |
| 2.1.9 | Time | 11:35 |
| 2.1.10 | Location | PHALABORWA |
| 2.1.11 | Start manhole no. | CHAMBER1(AIR VALVE) |
| 2.1.12 | Start depth | |
| 2.1.13 | Start cover level | |
| 2.1.14 | Start invert level | 2.64 |
| 2.1.15 | Finish manhole no. | AIR VALVE |
| 2.1.16 | Finish depth | |
| 2.1.17 | Finish cover level | |
| 2.1.18 | Finish invert level | 2.84 |
| 2.1.19 | Use of Drain | (Z) Not Known |
| 2.1.20 | Direction | (D) Survey downstream (camera pointing with flow) |
| 2.1.21 | Size 1 (diameter/height) | 560mm |
| 2.1.22 | Size 2 (width) | |
| 2.1.23 | Shape | (C) Circular |
| 2.1.24 | Material | (ST) Steel |
| 2.1.25 | Lining | |
| 2.1.26 | Pipe length | 150m |
| 2.1.27 | Total length | 9500m |
| 2.1.28 | Year laid | N/A |
| 2.1.29 | Video cassette number | |
| 2.1.30 | Comments: General | |
| 2.1.31 | Purpose | (Z) Not Known |
| 2.1.32 | Sewer category | (Z) Not Known |
| 2.1.33 | Pre-cleaning | (N) No |
| 2.1.34 | Weather | |
| 2.1.35 | Location code | |
| 2.1.36 | Further location details | |





2.2 Diagram

[page 1/1]



2.3 Observations

| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 0.0 | (ST) Start of survey | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_40_30_698.jpg 2023-08-29 11:40:30 0.00m -3.3°  |
| | AIRVALVE2 | 0:00:03 |
| 10.2 | (GO) General observation at this point | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_41_42_740.jpg 2023-08-29 11:41:42 10.16m -9.3°  |
| | PIPE CONDITIONN | 0:00:54 |
| 43.6 | (GO) General observation at this point | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_44_08_845.jpg 2023-08-29 11:44:08 43.65m -8.0°  |
| | PIPE CONDITION | 0:03:03 |
| 56.6 | (GO) General observation at this point | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_45_35_483.jpg 2023-08-29 11:45:35 56.58m -4.7°  |
| | PIPE JOINT | 0:04:07 |
| 57.3 | (CN) Connection at ... o'clock, diameter ...mm | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_47_08_925.jpg 2023-08-29 11:47:08 57.31m -4.4°  |
| 02 | Clock At/From: 02 Diameter/Dimension: N/A | |
| | CONNECTION | 0:04:36 |

| Distance | Condition code and attributes | Photo Ref |
|-----------------|---|---|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 72.2 | (D) Deformed sewer ...% Percentage: 5% | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_48_55_066.jpg 2023-08-29 11:48:54 72.15m -3.9°  |
| | DEFORMED PIPE | 0:05:57 |
| 121.4 | (GO) General observation at this point | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_53_05_922.jpg 2023-08-29 11:53:05 121.44m -2.7°  |
| | PIPE CONDITION | 0:09:37 |
| 130.2 | (D) Deformed sewer ...% Percentage: 5% | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_54_33_902.jpg 2023-08-29 11:54:33 130.24m -2.7°  |
| | DEFORMED PIPE | 0:10:38 |
| 161.7 | (GO) General observation at this point | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-11_57_34_054.jpg 2023-08-29 11:57:33 161.66m -3.8°  |
| | PIPE CONDITION | 0:13:11 |
| 193.9 | (GO) General observation at this point | ./2023-08-29-12-00-49/2023-08-29-12-00-49_2023_08_29-12_00_49_303.jpg 2023-08-29 12:00:49 193.90m -3.1°  |
| | PIPE CONDITION | 0:16:17 |


| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 214.4 | (GO) General observation at this point | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-12_03_22_997.jpg  |
| | | |
| | | |
| | WATER INSIDE PIPE | 0:18:33 |
| 215.9 | (CU) Camera under water | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-12_04_27_741.jpg  |
| | | |
| | | |
| | CAN NOT SEE CONDITION OF THE PIPE | 0:18:59 |
| 216.6 | (SA) Survey abandoned | ./2023-08-29-11-35-09/2023-08-29-11-35-09_2023_08_29-12_05_17_312.jpg  |
| | | |
| | | |
| | CAMERA UNDER WATER CAN NOT SEE CONDITION OF THE PIPE | 0:19:17 |

2.4 Photographs

(ST) Start of survey

2023-08-29 11:40:30

0.00m -3.3°




./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg

(GO) General observation at this point

2023-08-29 11:41:42

10.16m -9.3°




./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg

(GO) General observation at this point

2023-08-29 11:44:08

43.65m -8.0°




./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg

(GO) General observation at this point

2023-08-29 11:45:35

56.58m -4.7°




./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg

(CN) Connection at ... o'clock, diameter ...mm

2023-08-29 11:47:08

57.31m -4.4°




./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg

(D) Deformed sewer ...%

2023-08-29 11:48:54

72.15m -3.9°



./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg

(GO) General observation at this point ./2023-08-29-11-35-09/2023-08-29-11-35-09/2023-08-29-11-53-05-121.44m -2.7° 22.jpg



(D) Deformed sewer ...% . /2023-08-29-11-35-09/2023-08-29-11-35-
2023-08-29 11:54:33 130.24m -2.7% 02.jpg



(GO) General observation at this point ./.2023-08-29-11-35-09/2023-08-29-11-35-09.jpg

2023_08_29_11:57:33 161.66m -3.8%



(GO) General observation at this point ./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg



(GO) General observation at this point ./2023-08-29-11-35-09/2023-08-29-11-35-09.jpg



(CU) Camera under water . /2023-08-29-11-35-09/2023-08-29-11-35-
2023-08-29 12:04:27 215.89m -1.2° 41.jpg




(SA) Survey abandoned

./2023-08-29-11-35-09/2023-08-29-11-35-
2.jpg



2.5 Inclination graph




3 Drain / Sewer Survey

3.1 Survey Header






| | | |
|--------|---------------------------|---|
| 3.1.1 | Surveyed by (Operator) | AKANI/DARREN |
| 3.1.2 | Contract no. | 1 |
| 3.1.3 | Job no. | |
| 3.1.4 | Catchment (Drainage area) | |
| 3.1.5 | Division | LEPELLE NORTHERN WATER |
| 3.1.6 | District | MOPANE |
| 3.1.7 | Pipeline length ref | 9500 |
| 3.1.8 | Date | 290823 |
| 3.1.9 | Time | 12:55 |
| 3.1.10 | Location | PHALABORWA |
| 3.1.11 | Start manhole no. | CHAMBER2(AIR VALVE) |
| 3.1.12 | Start depth | |
| 3.1.13 | Start cover level | |
| 3.1.14 | Start invert level | 2.72 |
| 3.1.15 | Finish manhole no. | AIR VALVE |
| 3.1.16 | Finish depth | |
| 3.1.17 | Finish cover level | |
| 3.1.18 | Finish invert level | 2.8 |
| 3.1.19 | Use of Drain | (Z) Not Known |
| 3.1.20 | Direction | (D) Survey downstream (camera pointing with flow) |
| 3.1.21 | Size 1 (diameter/height) | 560mm |
| 3.1.22 | Size 2 (width) | |
| 3.1.23 | Shape | (C) Circular |
| 3.1.24 | Material | (ST) Steel |
| 3.1.25 | Lining | |
| 3.1.26 | Pipe length | N/Am |
| 3.1.27 | Total length | 9500m |
| 3.1.28 | Year laid | N/A |
| 3.1.29 | Video cassette number | |
| 3.1.30 | Comments: General | |
| 3.1.31 | Purpose | (Z) Not Known |
| 3.1.32 | Sewer category | (Z) Not Known |
| 3.1.33 | Pre-cleaning | (N) No |
| 3.1.34 | Weather | |
| 3.1.35 | Location code | |
| 3.1.36 | Further location details | |






3.2 Diagram


[page 1/1]




3.3 Observations


| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 10.4 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-12_58_12_421.jpg 2023-08-29 12:58:12 10.45m -8.3°  |
| | PIPE CONDITION | 0:01:00 |
| 27.1 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-12_59_33_741.jpg 2023-08-29 12:59:33 27.07m -5.2°  |
| | PIPE CONDITION | 0:02:05 |
| 36.5 | (DE) Debris ...% cross-sectional area loss Percentage: 3% | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_00_33_338.jpg 2023-08-29 13:00:33 36.55m -2.4°  |
| | RUST IN THE PIPE | 0:02:52 |
| 73.4 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_03_57_446.jpg 2023-08-29 13:03:57 73.43m 0.9°  |
| | PIPE CONDITION | 0:05:31 |
| 98.1 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_06_02_382.jpg 2023-08-29 13:06:02 98.14m -2.5°  |
| | PIPE CONDITION | 0:07:20 |


| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 135.9 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_09_14_425.jpg 2023-08-29 13:09:14 135.93m 1.8°  |
| | CONDITION OF THE PIPE | 0:10:15 |
| 161.4 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_11_59_550.jpg 2023-08-29 13:11:59 161.39m 1.8°  |
| | CONDITION OF THE PIPE | 0:12:39 |
| 188.8 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_15_14_802.jpg 2023-08-29 13:15:14 188.81m 3.4°  |
| | CONDITION OF THE PIPE | 0:15:34 |
| 206.1 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_17_38_253.jpg 2023-08-29 13:17:38 206.06m 3.2°  |
| | CONDITION OF THE PIPE | 0:17:33 |
| 224.7 | (GO) General observation at this point | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_21_15_007.jpg 2023-08-29 13:21:14 224.72m 3.2°  |
| | CONDITION OF THE PIPE | 0:20:49 |


| Distance | Condition code and attributes | Photo Ref |
|-----------------|-------------------------------------|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 241.1 | (SA) Survey abandoned | ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_25_01_923.jpg  |
| | | |
| | | |
| | CRAWLER STUCK DUE TO PIPE CONDITION | 0:24:16 |

3.4 Photographs

(GO) General observation at this point
 ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_25_01_923.jpg


(GO) General observation at this point
 ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_25_01_923.jpg


(DE) Debris ...% cross-sectional area loss
 ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_25_01_923.jpg


(GO) General observation at this point
 ./2023-08-29-12-55-16/2023-08-29-12-55-16_2023_08_29-13_25_01_923.jpg


(GO) General observation at this point
./2023-08-29-12-55-16/2023-08-29-12-55-16.jpg




(GO) General observation at this point
./2023-08-29-12-55-16/2023-08-29-12-55-16.jpg



(GO) General observation at this point
./2023-08-29-12-55-16/2023-08-29-12-55-16.jpg



(GO) General observation at this point
./2023-08-29-12-55-16/2023-08-29-12-55-16.jpg



(GO) General observation at this point
./2023-08-29-12-55-16/2023-08-29-12-55-16.jpg



(GO) General observation at this point
./2023-08-29-12-55-16/2023-08-29-12-55-16.jpg




(SA) Survey abandoned

./2023-08-29-12-55-16/2023-08-29-12-55-23.jpg



3.5 Inclination graph




4 Drain / Sewer Survey






4.1 Survey Header


| | | |
|--------|---------------------------|--|
| 4.1.1 | Surveyed by (Operator) | AKANI/DARREN |
| 4.1.2 | Contract no. | 1 |
| 4.1.3 | Job no. | |
| 4.1.4 | Catchment (Drainage area) | |
| 4.1.5 | Division | LEPELLE NORTHERN WATER |
| 4.1.6 | District | MOPANE |
| 4.1.7 | Pipeline length ref | 9500 |
| 4.1.8 | Date | 290823 |
| 4.1.9 | Time | 13:49 |
| 4.1.10 | Location | PHALABORWA |
| 4.1.11 | Start manhole no. | CHAMBER2(AIR VALVE) |
| 4.1.12 | Start depth | |
| 4.1.13 | Start cover level | |
| 4.1.14 | Start invert level | 2.72 |
| 4.1.15 | Finish manhole no. | AIR VALVE |
| 4.1.16 | Finish depth | |
| 4.1.17 | Finish cover level | |
| 4.1.18 | Finish invert level | 2.83 |
| 4.1.19 | Use of Drain | (Z) Not Known |
| 4.1.20 | Direction | (U) Survey upstream (camera pointing against flow) |
| 4.1.21 | Size 1 (diameter/height) | 560mm |
| 4.1.22 | Size 2 (width) | |
| 4.1.23 | Shape | (C) Circular |
| 4.1.24 | Material | (ST) Steel |
| 4.1.25 | Lining | |
| 4.1.26 | Pipe length | N/Am |
| 4.1.27 | Total length | 9500m |
| 4.1.28 | Year laid | N/A |
| 4.1.29 | Video cassette number | |
| 4.1.30 | Comments: General | |
| 4.1.31 | Purpose | (Z) Not Known |
| 4.1.32 | Sewer category | (Z) Not Known |
| 4.1.33 | Pre-cleaning | (N) No |
| 4.1.34 | Weather | |
| 4.1.35 | Location code | |
| 4.1.36 | Further location details | |

4.2 Diagram



4.3 Observations

| Distance | Condition code and attributes | Photo Ref |
|-----------------|---|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 14.0 | (GO) General observation at this point | ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-13_53_32_529.jpg 2023-08-29 13:53:32 14.01m -3.0°  |
| | CONDITION OF THE PIPE | 0:01:02 |
| 24.5 | (GO) General observation at this point | ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-13_54_40_604.jpg 2023-08-29 13:54:40 24.47m -4.6°  |
| | CONDITION OF THE PIPE | 0:01:44 |
| 60.8 | (GO) General observation at this point | ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-13_57_29_062.jpg 2023-08-29 13:57:29 60.78m -8.5°  |
| | CONDITION OF THE PIPE | 0:04:09 |
| 96.0 | (GO) General observation at this point | ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-14_00_17_400.jpg 2023-08-29 14:00:17 96.00m -7.6°  |
| | CONDITION OF THE PIPE | 0:06:32 |
| 142.5 | (SA) Survey abandoned | ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-14_05_29_749.jpg 2023-08-29 14:05:29 142.46m -12.0°  |
| | CRAWLER CAN NOT SEE CONDITION OF THE PIPE,PIPE FILLED WITH WATER. | 0:10:21 |


| Distance | Condition code and attributes | Photo Ref |
|-----------------|---|---|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 142.8 | (CU) Camera under water | ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-14_03_59_422.jpg |
| | | 2023-08-29 14:03:59 142.84m -12.8° |
| | |  |
| | CRAWLER UNDER WATER,CAN NOT SEE CONDITION OF THE PIPE | 0:09:52 |

4.4 Photographs

(GO) General observation at this point
 ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-14_03_59_422.jpg

2023-08-29 13:53:32
 14.01m -3.0°
 

(GO) General observation at this point
 ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-14_03_59_422.jpg

2023-08-29 13:54:40
 24.47m -4.6°
 

(GO) General observation at this point
 ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-14_03_59_422.jpg

2023-08-29 13:57:29
 60.78m -8.5°
 

(GO) General observation at this point
 ./2023-08-29-13-49-14/2023-08-29-13-49-14_2023_08_29-14_03_59_422.jpg

2023-08-29 14:00:17
 96.00m -7.6°
 

(SA) Survey abandoned

/2023-08-29-13-49-14/2023-08-29-13-49-14.jpg




(CU) Camera under water

/2023-08-29-13-49-14/2023-08-29-13-49-14.jpg



4.5 Inclination graph




5 Drain / Sewer Survey





5.1 Survey Header


| | | |
|--------|---------------------------|--|
| 5.1.1 | Surveyed by (Operator) | AKANI/DARREN |
| 5.1.2 | Contract no. | 1 |
| 5.1.3 | Job no. | |
| 5.1.4 | Catchment (Drainage area) | |
| 5.1.5 | Division | LEPELLE NORTHERN WATER |
| 5.1.6 | District | MOPANE |
| 5.1.7 | Pipeline length ref | 9500 |
| 5.1.8 | Date | 300823 |
| 5.1.9 | Time | 09:50 |
| 5.1.10 | Location | PHALABORWA |
| 5.1.11 | Start manhole no. | CHAMBER3(AIR VALVE) |
| 5.1.12 | Start depth | |
| 5.1.13 | Start cover level | |
| 5.1.14 | Start invert level | 2.61 |
| 5.1.15 | Finish manhole no. | AIR VALVE |
| 5.1.16 | Finish depth | |
| 5.1.17 | Finish cover level | |
| 5.1.18 | Finish invert level | 2.72 |
| 5.1.19 | Use of Drain | (Z) Not Known |
| 5.1.20 | Direction | (U) Survey upstream (camera pointing against flow) |
| 5.1.21 | Size 1 (diameter/height) | 560mm |
| 5.1.22 | Size 2 (width) | |
| 5.1.23 | Shape | (C) Circular |
| 5.1.24 | Material | (ST) Steel |
| 5.1.25 | Lining | |
| 5.1.26 | Pipe length | N/Am |
| 5.1.27 | Total length | 9500m |
| 5.1.28 | Year laid | N/A |
| 5.1.29 | Video cassette number | |
| 5.1.30 | Comments: General | |
| 5.1.31 | Purpose | (Z) Not Known |
| 5.1.32 | Sewer category | (Z) Not Known |
| 5.1.33 | Pre-cleaning | (N) No |
| 5.1.34 | Weather | |
| 5.1.35 | Location code | |
| 5.1.36 | Further location details | |

5.2 Diagram




5.3 Observations

| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 0.0 | (GO) General observation at this point | |
| | | |
| | | |
| | VT No. 93384881.mp4 STARTS | 0:00:02 |
| 19.4 | (GO) General observation at this point | ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_00_18_470.jpg 2023-08-30 10:00:18 19.36m -3.6° |
| | |  |
| | COONDITION OF THE PIPE | 0:01:23 |
| 20.1 | (GO) General observation at this point | ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_42_45_060.jpg 2023-08-30 10:42:45 20.06m -5.9° |
| | |  |
| | CONDITION OF THE PIPE | 0:01:23 |
| 90.9 | (GO) General observation at this point | ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_47_33_662.jpg 2023-08-30 10:47:33 90.93m -7.6° |
| | |  |
| | CONDITION OF THE PIPE | 0:05:55 |
| 141.0 | (GO) General observation at this point | ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_51_16_927.jpg 2023-08-30 10:51:16 140.97m -4.4° |
| | |  |
| | CONDITION OF THE PIPE | 0:09:22 |


| Distance | Condition code and attributes | Photo Ref |
|-----------------|---|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 162.1 | (SA) Survey abandoned | ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_54_45_655.jpg |
| | | <div> <div>2023-08-30 10:54:45</div> <div>162.13m -7.3°</div>  </div> |
| | CRAWLER STUCK DUE TO DEBRIS IN THE PIPE | 0:12:30 |

5.4 Photographs


(GO) General observation at this point
 ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_00_18_650.jpg

2023-08-30 10:00:18
 19.36m -3.6°
 


(GO) General observation at this point
 ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_42_45_660.jpg

2023-08-30 10:42:45
 20.06m -5.9°
 

(GO) General observation at this point
 ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_47_33_652.jpg

2023-08-30 10:47:33
 90.93m -7.6°
 

(GO) General observation at this point
 ./2023-08-30-09-50-33/2023-08-30-09-50-33_2023_08_30-10_51_16_627.jpg


2023-08-30 10:51:16
 140.97m -4.4°
 

(SA) Survey abandoned

/2023-08-30-09-50-33/2023-08-30-09-50-



5.5 Inclination Graph




6 Drain / Sewer Survey

6.1 Survey Header






| | | |
|--------|---------------------------|---|
| 6.1.1 | Surveyed by (Operator) | AKANI/DARREN |
| 6.1.2 | Contract no. | 1 |
| 6.1.3 | Job no. | |
| 6.1.4 | Catchment (Drainage area) | |
| 6.1.5 | Division | LEPELLE NORTHERN WATER |
| 6.1.6 | District | MOPANE |
| 6.1.7 | Pipeline length ref | 9500 |
| 6.1.8 | Date | 300823 |
| 6.1.9 | Time | 11:15 |
| 6.1.10 | Location | PHALABORWA |
| 6.1.11 | Start manhole no. | CHAMBER3(AIR VALVE) |
| 6.1.12 | Start depth | |
| 6.1.13 | Start cover level | |
| 6.1.14 | Start invert level | 2.61 |
| 6.1.15 | Finish manhole no. | AIR VALVE |
| 6.1.16 | Finish depth | |
| 6.1.17 | Finish cover level | |
| 6.1.18 | Finish invert level | 2.86 |
| 6.1.19 | Use of Drain | (Z) Not Known |
| 6.1.20 | Direction | (D) Survey downstream (camera pointing with flow) |
| 6.1.21 | Size 1 (diameter/height) | 560mm |
| 6.1.22 | Size 2 (width) | |
| 6.1.23 | Shape | (C) Circular |
| 6.1.24 | Material | (ST) Steel |
| 6.1.25 | Lining | |
| 6.1.26 | Pipe length | N/Am |
| 6.1.27 | Total length | 9500m |
| 6.1.28 | Year laid | N/A |
| 6.1.29 | Video cassette number | |
| 6.1.30 | Comments: General | |
| 6.1.31 | Purpose | (Z) Not Known |
| 6.1.32 | Sewer category | (Z) Not Known |
| 6.1.33 | Pre-cleaning | (N) No |
| 6.1.34 | Weather | |
| 6.1.35 | Location code | |
| 6.1.36 | Further location details | |

6.2 Diagram

[page 1/1]



6.3 Observations


| Distance | Condition code and attributes | Photo Ref |
|-----------------|--|--|
| Cont. Defect | | |
| Clock (At – To) | | |
| Joint | Remarks | Video Ref |
| 5.0 | (GO) General observation at this point | ./2023-08-30-11-15-06/2023-08-30-11-15-06_2023_08_30-11_18_41_695.jpg 2023-08-30 11:18:41 5.03m -3.5°  |
| | CONDITION OF THE PIPE | 0:00:32 |
| 13.6 | (GO) General observation at this point | ./2023-08-30-11-15-06/2023-08-30-11-15-06_2023_08_30-11_22_11_866.jpg 2023-08-30 11:22:11 13.61m -6.0°  |
| | CONDITION OF THE PIPE | 0:01:52 |
| 55.3 | (GO) General observation at this point | ./2023-08-30-11-15-06/2023-08-30-11-15-06_2023_08_30-11_35_49_679.jpg 2023-08-30 11:35:49 55.26m -5.4°  |
| | CONDITION OF THE PIPE | 0:05:09 |
| 77.8 | (CU) Camera under water | ./2023-08-30-11-15-06/2023-08-30-11-15-06_2023_08_30-11_37_50_069.jpg 2023-08-30 11:37:49 77.82m -5.0°  |
| | CAMERA UNDER WATER | 0:06:46 |
| 77.9 | (SA) Survey abandoned | ./2023-08-30-11-15-06/2023-08-30-11-15-06_2023_08_30-11_38_25_436.jpg 2023-08-30 11:38:25 77.87m -5.5°  |
| | CAMERA UNDER WATER | 0:06:59 |

6.4 Photographs

(GO) General observation at this point

2023-08-30 11:18:41

5.03m -3.5°




./2023-08-30-11-15-06/2023-08-30-11-15-06.jpg

(GO) General observation at this point

2023-08-30 11:22:11

13.61m -6.0°




./2023-08-30-11-15-06/2023-08-30-11-15-06.jpg

(GO) General observation at this point

2023-08-30 11:35:49

55.26m -5.4°




./2023-08-30-11-15-06/2023-08-30-11-15-06.jpg

(CU) Camera under water

2023-08-30 11:37:49

77.82m -5.0°




./2023-08-30-11-15-06/2023-08-30-11-15-06.jpg

(SA) Survey abandoned


2023-08-30 11:38:25

77.87m -5.5°



./2023-08-30-11-15-06/2023-08-30-11-15-06.jpg

6.5 Inclination graph



11.5 Appendix 5 : Trenchless Pipeline Relining Technology

Pipe-in Liner™

Trenchless Rehabilitation on Pressure Pipes

∴ Asoe, provider of trenchless pipe rehabilitation solutions

Asoe Hose Manufacturing, Inc. develops different types of trenchless pipe rehabilitation solutions to pressure pipes. Pipe-in Liner is the easiest to install.

Pipe-in Liner is a Fabric Reinforced Flexible Plastic Hose (FRFPFH). The basic installation procedure is as follows:

1. Fold firstly Pipe-in Liner into U-shape
2. Pull the liner into the host pipes
3. Expand the liner in the host pipes

Then the Pipe-in liner will work as a leakage-free liner inside the host pipes.

Pipe-in Liners are classified into four different series: Pipe-in Liner W Series, Pipe-in Liner O Series, Pipe-in Liner G series, and Pipe-in Liner H series. Pipe-in Liner W series are used to rehabilitate pressure pipelines, including water main pipes and force mains at normal temperature. Pipe-in Liner O series are used to rehabilitate oil pipes both onshore and offshore. Pipe-in Liner G series are used to rehabilitate gas pipes both onshore and offshore. Pipe-in liner H series are used to

rehabilitate pipes in municipal heat system. Pipe-in liner H series can resist a temperature up to 95° C (203° F); furthermore, Asoe is the first company in the world to develop this type of solution to rehabilitate hot water pipes.

Besides liners, Asoe also supplies complete solutions and accessory equipment, including couplings to connect Pipe-in Liner with host pipes, equipment to install couplings, and technical consulting etc.

Pipe-in Liner solution is a structurally independent rehabilitation technology. There is no connection between the host pipe and the liner; the liner works independently from the host pipe. The liner is rigid and maintains the round shape inside the host pipes when there is a vacuum inside the host pipe or when there is temporary external pressure on the host pipe.

Pipe-in Liner is flexible and can easily rehabilitate bent pipes of less than 45° to 90° with a 5D radius.

Also, Pipe-in Liner Technology only requires coarse pipe cleaning.



Corrosion-resistant



Quick Installation




Holds High Pressure Internally

0 Pipe-in Liner™ for trenchless pipe rehabilitation

:: Application of Pipe-in Liners


Pipe-in Liners are fabric reinforced flexible plastic pipes (FRFP) used for trenchlessly rehabilitating four different types of pressure pipes:
 Pipe-in Liner W Series (rehabilitating water main pipes and other water pipes with inside pressure);
 Pipe-in Liner O Series (rehabilitating oil pipes);
 Pipe-in Liner G Series (rehabilitating gas pipes);
 Pipe-in Liner H Series (rehabilitating hot water pipes).

:: Technical Specification of Pipe-in Liners



Pipe-in Liner W Series

Nominal ID of host pipes: 50mm (2 inches)— 800mm (32 inches)
 Maximum length of each installation: up to 4000m (13,000ft)
 Maximum operating pressure: 1.0 - 4.0 Mpa (150psi-600psi)
 Maximum bursting pressure: 3.0-12.0 Mpa (450psi-1800psi)
 Installation mode: Pull in U-shape Liners
 Raw materials: high tenacity fabric reinforcement layer, abrasion-resistant PE cover, PE tube (NSF61 certified, Potable Water Safety approved by NHFPC of China)
 Abrasion resistance (DIN53516) : 10.5 mm³
 Temperature of media: -40°C to 70°C (-40°F to 158°F)
 Wall thickness: 6mm-8mm (0.236-0.315 inch)
 Trenchless solution type: Semi-structural pipe rehabilitation
 Pulling speed: up to 400m/h
 Service life duration: 50 years



Pipe-in Liner O Series

Nominal ID of host pipes: 50mm (2 inches)— 800mm (32 inches)
 Maximum length of each installation: up to 4000m (13,000ft)
 Maximum operating pressure: 1.0 - 4.0 Mpa (150psi-600psi)
 Maximum bursting pressure: 3.0-12.0 Mpa (450psi-1800psi)
 Installation mode: Pull in U-shape Liners
 Raw Materials: high tenacity fabric reinforcement layer, abrasion resistant PE cover, oil-resistant PU tube or oil and heat-resistant PVDF tube (PVDF is expensive relatively)
 Abrasion resistance (DIN53516) : 10.5 mm³
 Temperature of media: -40°C to 70°C (-40°F to 158°F)
 Wall thickness: 6mm-8mm (0.236-0.315 inch)
 Trenchless solution type: Semi-structural pipe rehabilitation
 Pulling speed: up to 400m/h
 Service life duration: 40 years



Pipe-in Liner G Series

Modified abrasion-resistant PE layer

Reinforcement fabric layer

Airtight PU layer

Nominal ID of host pipes: 50mm (2 inches)— 800mm (32 inches)

Maximum length of each installation: up to 4000m (13,000ft)

Maximum operating pressure: 1.0 - 4.0 Mpa (150psi-600psi)

Maximum bursting pressure: 3.0-12.0 Mpa

Installation mode: Pull in U-shape Liners

Raw Materials: high tenacity fabric reinforcement layer, abrasion resistant PE cover, airtight PU tube

Abrasion resistance (DIN53516) : 10.5 mm³


Temperature of media: -40°C to 70°C (-40°F to 158°F)

Wall thickness: 6mm-8mm (0.236-0.315 inch)

Trenchless solution type: Semi-structural pipe rehabilitation

Pulling speed: up to 400m/h

Service life duration: 40 years



Pipe-in Liner H Series

Abrasion and heat resistant PUX layer

Reinforcement fabric layer

Abrasion and heat resistant PUX layer

Nominal ID of host pipes: 50mm (2 inches)— 800mm (32 inches)

Maximum length of each installation: up to 4000m (13,000ft)

Maximum operating pressure: 1.0 - 4.0 Mpa (150psi-600psi)

Maximum bursting pressure: 3.0-12.0 Mpa (450psi-1800psi)

Installation mode: Pull in U-shape Liners

Raw Materials: high tenacity fabric reinforcement layer, heat-resistant PUX cover, heat-resistant PUX tube

Abrasion resistance (DIN53516) : 10.5 mm³

Temperature of media: -40°C to 95°C (-40°F to 203°F)

Wall thickness: 6mm-8mm (0.236-0.315 inch)

Trenchless solution type: Semi-structural pipe rehabilitation

Pulling speed: up to 400m/h

Service life duration: 40 years

○ Information on host pipes needed for choosing correct liners:

In order to purchase correct liners to rehabilitate host pipes, the following information is required:


1. Normal operating pressure and temperature;
2. Media transferred inside the host pipes, such as water, oil, gas, hot water, chemicals etc.
3. Materials and actual ID of host pipes, number of bends, degrees of bends, etc.

4. The length of each section of host pipes which are supposed to be rehabilitated.

Pipe-in Liners withstand the inside pressure, but Pipe-in Liners cannot resist the external load. However, the host pipes must be able to bear the external load. If the host pipes collapse, Pipe-in Liner solution is not recommended.

PILC Couplings

:: PILC couplings for trenchless pipe rehabilitation



PILC couplings contain three parts: outer flange tube, expansion ferrule, inner pushing tube.

Outer flange tube is made of carbon steel coated with epoxy powder coating and is to fix PILC couplings onto host pipes.

Expansion ferrule is made of carbon steel and is to prevent the lining from slipping and abrasion.

Inner pushing tube is made of carbon steel or stainless steel according to media transferred. It is to fasten the liners onto the flange tube.

Size of couplings: DN50- DN800 (2-32 inches).

:: Features

Reliable design ensures the liner to be locked tightly onto PILC couplings with no leaking.

No loss in water flow because the inside diameter of inner pushing tubes are the same as that of liners.

No friction loss at the connecting point of liners and inner pushing tube.

Easy to install. Hydraulic equipment is needed to install couplings.



Expansion ferrule Accessory flange Pipe-in Liner
Inner pushing tube Outer flange tube Host Pipe

:: Other suggestions on PILC installation

Flanges are recommended to be used to connect the host pipes with PILC couplings although it is possible to weld the PILC directly onto host pipe. Flanges are recommended to be used between PILC couplings and transition tubes.

Flanges are recommended to be used between host pipes and transition tubes, although it is possible to weld the PILC directly onto host pipe.

:: PILC installation services

Hydraulic installation equipment can be purchased or leased from Asoe. Contractual engineers are suggested to get some training by Asoe. Asoe's installation engineers can be hired to help contractors to install PILC couplings.



0 Installation

- ⊙ Choose section of host pipes to be rehabilitated
- ⊙ Install by-pass hoses in order to keep transferring flow during rehabilitating
- ⊙ Dig construction pits at two ends
- ⊙ Inspect pipes with a mobile TV camera and analysis of video recordings
- ⊙ Mechanical coarse cleaning of host pipes with scraper pigs
- ⊙ Clean host pipes by water jetting
- ⊙ Position Pipe-in Liners at the start pit and the pulling winch at destination pit
- ⊙ The pulling head shall be installed onto the liner.
- ⊙ Hose guides shall be installed.
- ⊙ Fold Pipe-in Liner into U-shape and bind the liner with scotch tape.
- ⊙ The liner shall be pulled into the host pipes.
- ⊙ PILC couplings shall be installed onto the host pipes.
- ⊙ Hydrostatic pressure test shall be completed.
- ⊙ Transition pipes shall be installed.
- ⊙ Then transferring fluid will be recovered.
- ⊙ Finally, remove the by-pass and close the pit.

0 Technical Advantages

It is a perfect solution for the pipeline rehabilitation projects, which involve host pipes that can't be repaired by the traditional remove-and-replace method.

Free of maintenance after the liner rehabilitation.

This pipe in liner method can be applied to the bended pipes of less than 45° bend to 90° with a 5D radius.

The Pipe In Liner can resist internal pressure independently.

The requirements of host pipes for working zones and conditions are low.

Low effects on the surrounding environment during liner installation.

No chemical epoxy resin applied and no air pollution emission.

The pipe in liner is a quick installation.

The pipe in liner can be applied to a long-distance installation from one access point.

0 Rehabilitation Applications

1. Water Mains and Force Mains
2. Onshore and Offshore Oil or Gas Pipelines
3. Chemical Pipelines
4. Water Heating System Pipelines

0 Reference of Projects



1. Gas pipeline rehabilitation in Mianyang, Sichuan, China.

Pipe-in Liner G series were installed in the gas pipelines with the ID 200mm. Totally two sections of gas pipes were rehabilitated with the total length 450 meters.

2. Water drainage pipelines rehabilitation in a water plant in Zhuhai, Guangdong, China.

Pipe-in Liner W series were installed in the water drainage pipelines with the ID 300mm. As many as three sections of water drainage pipes were rehabilitated with the total length 120 meters.

3. Gas pipeline rehabilitation in Fushun, Liaoning, China.

Pipe-in Liner G series were installed in the gas pipe with the ID 400mm. Two sections of gas pipes were rehabilitated with the total length 280 meters.

4. Water main pipes rehabilitation in Xiamen, Fujian, China.

As many as four sections of DN500 water pipes were rehabilitated by Pipe-in Liner W Series with the total length 600 meters.

5. Oil pipeline rehabilitation in Venezuela.

Pipe-in Liner O series were installed in the oil pipes with the ID 100mm. One section of oil pipes was rehabilitated with the total length 660m.

6. Water pipelines rehabilitating in Rostov, a nuclear plant in Russia.

Pipe-in Liner W series were installed in the water pipelines with the ID 300mm. As many as ten sections of water pipes were rehabilitated with the total length 600m.

7. One project of DN700 water pipes rehabilitation in China is undergoing.

