

TRANSNET

delivering freight reliably

CONDITION ASSESSEMENT OF THE OVERVAAL TUNNEL

10 November 2023

1. Executive Summary

- Assessments done to date
- Assessment findings
- Risks associated with defects

2. Project Overview

- Project Aim
- Project Scope
- Project Benefits

3. Condition Assessment

- Findings from routine maintenance
- Method used for assessment
- Assessment results

4. Structural Assessment

- Method used for assessment
- Assessment result

Assessments done to date

- IM2000 inspections
- Routine/ daily visual inspections include trolley inspections
- A detailed visual inspections was done during the 2013 shutdown which focused on structural defects on the track slab and tunnel lining.
- Design of the second Overvaal tunnel
- A comprehensive structural condition assessment was done in 2018 using digital tools to capture all structural defects on the tunnel components
- Structural health monitoring (SHM) was implemented on the identified defects to understand the tunnel's behavior under its current condition.

Assessment findings

- The existing tunnel has a few design flaws that lead to some of the challenges experienced today i.e. no water-proof on tunnel walls, single wall lining design, etc.
- The Track Quality Index (TQI) inside the tunnel is greater than target. S-Line TQI target = 6 and the Overvaal TQI = 14
- Water seepage through tunnel walls was observed. It was clear that it is ground water that has found a way through the walls.
- This is caused by the lack of water-proofing on tunnel walls and a high water table levels in the affected area due to a river stream that runs above the tunnel
- Cavities were observed at the junction of the track slab and the inside of one the drains. Only a few of these areas are visible, there could be more cavities underneath the slab.
- A total of 2 327 cracks were observed on the tunnel components, ranging between the widths of 0.1mm to 5.5mm. Critical crack width on railway track slabs is $\geq 0.3\text{mm}$
- From SHM, deformation of the tunnel lining was recorded at KM 23+658. this is due to the hydrostatic pressure due to high water table at this section. Significant vertical slab deflection was observed at KM 24+000


Risks associated with defects

- The poor TQI state could lead to derailments or hook-ups inside the tunnel
- Cavities underneath the slab (known & unknown) create uneven load distribution resulting in the formation of cracks, excessive slab deflection or worse, slab breaks under load leading to derailment
- The cracks allow water to seep through the walls causing rust on the steel reinforcement, reducing capacity to withstand tension forces, weakening the structural integrity of the lining & track slab
- Seismic actions(natural occurrence) from the identified fault zones could have devastating effects on the already weakened structural integrity

Project Aim:

- Collect baseline data to study structural behavior
- Protect Transnet against potential claims during construction

Project Scope:



Project Benefits


- Holistic understanding of the tunnel components' structural integrity
- Baseline data collection to enable Predictive Maintenance Strategy (Inline with Transnet's 4.0 theme)
- Effecting progress towards establishing safety limits for safe construction of the second Overvaal Tunnel

STRUCTURAL CONDITION ASSESSMENT

Findings from Routine Condition Assessment



ERM



RCB

Western Portal


Eastern Portal

- Perway - IM2000 inspection results
- Civils - Visual inspection including trolley inspections

TUNNEL CHALLENGES LEGEND

- Tunnel longitudinal profile
- Track slab pump action
- TQI exceed STD by +3
- Stagger C-Exceptions
- Height C-Exceptions
- - - Fault zone
- ★ Exposed wire mesh
- ▼ Water seepage through lining
- ▼ PVC channels over OHTE
- ☁ Concrete delamination on Tunnel lining
- Concrete Lining Heaving

Findings from Routine Condition Assessment



- S-Line classification: Adopted TQI target = 6
- Increased variance in TQI specifically in the Overvaal tunnel.
- TQI range is relatively similar before and after the tunnel.

Digital Condition Assessment



- Semi-automatic 360° UHD imaging system was used to capture the tunnel lining's condition.
- The assembled HD orthophotography was used to perform the remote inspection of the tunnel lining
- The first 300m of the track slab was visually inspected and used as a reference and scale.

Benefits

- Digital assessment of defects
- Off-site tunnel inspection
- Can be fully automated**



Image of tunnel lining captured for inspection

Tunnel Lining Condition

Defect	Quantity	Total length/Area
Cracks	2230	5887.9m
Horizontal	418	2313.3m
Vertical	1684	3065.8m
Diagonal	100	246.9m
Horizontal + Diagonal	2	6.9m
Horizontal + Vertical	26	255m
Crazing	13	186.4m²
Water Seepage	96	1607.6m²
Delamination	2	0.04m²
Miscellaneous defects	38	3252m²
Spalling	2	7.8m ²
Efflorescence	21	772.8m ²
Efflorescence + Seepage	14	2471m ²



- Significant cracks on the light density reinforced tunnel lining are mainly induced by the rock mass movement as well as the hydrostatic pressure
- Interconnected cracks presents a risk of collapse
- No corrosion visible: Potential corrosion none destructive test recommended
- Evolution of the cracks is being monitored

Track Slab Condition





Defect	Quantity	Total length/Area
Cracks	97	62.8m
Transversal	94	47m
Longitudinal	3	15.8
Crazing	0	0
Water Seepage	1	0.3m²
Delamination	10	1.5m²
Miscellaneous defects	7	21.95m²
Spalling	5	0.25m ²
Efflorescence	2	21.7m ²
Efflorescence + Seepage	0	0

Findings

- No critical cracks observed
- Water seepage from cracks with width > 2mm posing a threat of corrosion of rebar
- Minor areas of de-bonding
- The movement is to be confirmed by the continuous condition monitoring

Track Slab Condition cont.



- 85% of the cracks have a width of less or equal to 1.3mm
- Only six (6) cracks have an opening ranging between 2mm to 4mm.
- 92% of the crack's lengths are less than 1m


Vulnerability of structures

Aim

- Study the vulnerability of existing structures in relation to proposed second tunnel excavation
- Determine the vibration limits for existing structures.



Structures	Distance from new tunnel (m)	Condition
Existing tunnel	25	<ul style="list-style-type: none"> • Major cracks on the tunnel lining due design flaws • Water seepage through the cracks
AfGRI Silos	1000	<ul style="list-style-type: none"> • Good condition (Small thin cracks) • No settlement
Cell C tower	159	<ul style="list-style-type: none"> • Good condition • No settlement
Community houses (lowest)	154	<ul style="list-style-type: none"> • Mud houses are in a poor condition; present a risk of collapsing.
Community houses (closest)	109	<ul style="list-style-type: none"> • Mud houses are in a poor condition; present a risk of collapsing.



Vulnerability = Hazard x Sensitivity

Hazard estimation


1. Deformation/Settlement hazard

- Influence zone = 40.6m (20.3m from center of new tunnel)
- The existing tunnel is affected by excavation
- $\Delta_{\max} = 33.6\text{mm}$

$$i = 0.35 \left(C + \frac{D}{2} \right)$$

$$i = 0.35 \left(110 + \frac{12,044}{2} \right)$$


$$i = 40,608\text{m}$$



2. Vibration hazard

- Influence zone: Drill and blast = 100m from center of new tunnel
TBM = 50m
- Only the existing tunnel will be affected by vibrations

Structure	Distance from new tunnel (m)	Level of signal expected PV (mm/s)		Hazard (Y/N)
		Drill & Blast	TBM	
Overvaal Tunnel	25	4	0.13	Y



Sensitivity estimation

1. Sensitivity of existing structures due to deformation (settlement)
 - Damage category of the Overvaal Tunnel is ***Structural***

Structures	Function	Geometrical & structural characteristics	Current Condition	Sensitivity to Deformation
Overvaal Tunnel	Railway tunnel	Underground structure with mixed type of reinforcement in cast in-situ concrete lining	Structural	Highly sensitive

2. Sensitivity of existing structures due to vibration
 - Sensitivity is based on the type of building, foundation & geology.

Structures	Type of structure	Type of foundation	Soil type
Overvaal Tunnel	Underground structure with mixed type of reinforcement in cast in-situ concrete lining	Class B	Type A

Vulnerability = Hazard x Sensitivity

Structures	Hazard			Sensitivity		Vulnerability
	Deformation	Vibration (TBM)	Vibration (Drill & Blast)	Deformation	Vibration	
Existing Overvaal tunnel	Yes – primary pattern <u>Trough area</u> S _{max} = 33,57mm i = 40,61m	Yes PV = 0,13mm/s	Yes PV = 4mm/s	Highly sensitive	Sensitive	Yes
AFGRI Silos	No	No	No	Moderately sensitive	Not sensitive	No
Cell C Tower	No	No	No	Moderately sensitive	Not sensitive	No
Community houses	No	No	No	Sensitive	Highly sensitive	No

Design Standards
1. SANS 10100: 2011
2. SANS 4866: 2011
3. EUROCODE EN 1997
4. AFTES RECOMMENDATIONS: GT16R1A1
5. DIN 4150-3 – GERMAN VIBRATION STANDARDS
6. USBM R18507 – BLASTING VIBRATIONS

TRANSNET



delivering freight reliably

THANK YOU

