



# **REHABILITATION OF MARETLWANE NORTH ASBESTOS MINE: RE-ADVERTISEMENT**

**CONTRACT MTK 19/2022**

**VOLUME 3**

**CONTRACT**

**PART 4:**

**SITE INFORMATION**



## C4 SITE INFORMATION

### GENERAL

This section describes the site at the time of tender to enable the tenderer to price their tender and to decide upon his method of working and programming and risks.

### CONTENTS

Clause	Description	Page no.
SI 1	SITE INFORMATION	SI.2
SI.2	SITE LOCATION	SI.2
SI.3	EXISTING CONDITIONS	SI.5
SI 4	SERVICES AND EXISTING INFRASTRUCTURE	SI.5
SI 5	SITE GEOLOGY	SI.7
SI 7	HEALTH AND SAFETY SPECIFICATION	SI.8
SI 8	ENVIRONMENTAL MANAGEMENT PLAN	SI.9



## **SI 1 SITE INFORMATION**

The mine site is approximately located at the coordinates 24°21'50.52"S and 30°17'3.03"E on the farm Streatham within the Greater Tubatse Local Municipality, approximately 45 kilometres from Burgersfort CBD and west of the Maretlwane village near the Penge Village within the Limpopo Province.

## **SI 2 SITE LOCATION**

Figure 1 provides a locality map and shows the access route to site. Travel northeast from the CBD on R37 for 5.1km. Turn right onto road to Praktiseer and travel for 10km until you reach a four way stop. Turn left onto road D 2537 and travel for 28km. The site is on the left. The site can be easily accessed with a 4x2.



**Figure 1: Maretlwane North locality map**



### SI 3 EXISTING CONDITIONS

The surrounding area was previously rehabilitated. Land use of the surrounding environment is largely wilderness area with natural vegetation. The vegetation is fairly scattered to dense and consists of mostly shrubs on steep slopes.



**Main Asbestos dump**





**Asbestos contaminated dump area**



**Adit to be closed**

#### **SI 4 SERVICES AND EXISTING INFRASTRUCTURE**

A direct access road is available and can be accessed with a 4x2. A passenger vehicle cannot drive into some sections due to overgrown vegetation. Potable water and electricity is not available on site.

The existing mining infrastructure to be demolished includes storage silos and operating buildings.



REHABILITATION OF MARETLWANE NORTH ASBESTOS MINE: RE-ADVERTSIEMENT  
(MTK 19/2022)



Volume 3

Part 4: Site Information

---



**Existing Storage Silo's to be demolished.**





## **SI 5 SITE GEOLOGY**

Geotechnical investigation is in progress.

## **SI 7 HEALTH AND SAFETY SPECIFICATION**

See attached (Appendix A)

## **SI 8 ENVIRONMENTAL MANAGEMENT PLAN**

See attached (Appendix B)



**APPENDIX A**  
**HEALTH AND SAFETY SPECIFICATION**



**APPENDIX B**  
**ENVIRONMENTAL MANAGEMENT PLAN**