

ANNEXURE A- DAMAGED PICTORIALS FOR THE KZN CORRIDOR -(PREQUALIFICATION OF CONTRACTORS)

CLUSTER ONE (Umlazi Corridor- Umlazi Montclair and Clairwood Station Cluster 1)

www.prasa.com

Be moved



prasa
PASSENGER RAIL AGENCY
OF SOUTH AFRICA

ANNEXURE A: PICTORIALS

		Cracked retaining wall, and walls that needs repainting.
		Rusty metal sheets, steel structure and damaged chairs
Umlazi Station		
		Vandalized toilets sinks with no taps. Rusty and faulty air conditioning system
		Damaged door and flooring in the waiting rooms that needs refinishing.

ANNEXURE A- DAMAGED PICTORIALS FOR THE KZN CORRIDOR -(PREQUALIFICATION OF CONTRACTORS)

CLUSTER TWO (Umlazi Corridor Tender- Dalbridge and Berea Station)

www.prasa.com

Be moved



prasa
PASSENGER RAIL AGENCY
OF SOUTH AFRICA

ANNEXURE A: PICTORIALS

		Missing metal sheets and damaged Ceiling.
		Missing Toilet Cistern pipes and taps with damaged floor tiles.
Dalbridge Station		
		Damaged Ceilings, and Platform that's needs repainting of lines and signage.
		Missing Urinals and sinks, Cisterns and plumbing pipes.
Berea Station		

ANNEXURE A- DAMAGED PICTORIALS FOR THE KZN CORRIDOR -(PREQUALIFICATION OF CONTRACTORS)

CLUSTER THREE Cluster 3: (Durban Station- Umlazi to Durban station)

ANNEXURE A: PICTORIALS

		Missing lights and signage that is no longer visible.
		Missing ceiling sheets and a leak that courses paint to peel. In this column.
		Missing plumbing system in the toilets and damaged ceiling.
Durban Station		

ANNEXURE A- DAMAGED PICTORIALS FOR THE KZN CORRIDOR –

(PREQUALIFICATION OF CONTRACTORS)

CLUSTER FOUR (Thembalihle and Bridge City Station) Kwa Mashu to Moses Mabhida station)

ANNEXURE A: PICTORIALS

		Damaged ceiling and roof leaks.
		Cracked glass door panel and peeling column tiles
Bridge City Station		
		Burnt rooms and toilets with missing plumbing system.
		Roof structure with missing metal sheeting's. Burnt turnstiles
Thembalihle Station		

ANNEXURE A- DAMAGED PICTORIALS FOR THE KZN CORRIDOR -(PREQUALIFICATION OF CONTRACTORS)

CLUSTER FIVE (Effingham, Kenville and Duffs road station KwaMashu to Moses Mabhida station)

www.prasa.com

Be moved



prasa
PASSENGER RAIL AGENCY
OF SOUTH AFRICA

ANNEXURE A: PICTORIALS

		Cracked benches damaged doors.
		Limited old signages
Effingham Station		
		Cracked walls and damaged floor tiles
		Steel structure with missing metal sheets and toilets with no doors and plumbing system.
Duffs Road Station		