

ANNEXURE A: PICTORIALS KNIGHTS

Vandalised Buildings and Infrastructure









Vandalised Bridge Staircase





Dilapidated Platform





Vandalised Structures



Dilapidated Pedestrian Bridge



PASSENGER RAIL AGENCY OF SOUTH AFRICA

ANNEXURE A: PICTORIALS KEMPTON PARK

1. Ticket sales point.











3. Cracked platform floor surface.



5. Leaking toilets.

4. Faded paint on steel structures



6. Corrugated sheeting barrier on platform.









8. Corrosion on platform bridge