

ANNEXURE A: PICTORIALS

		Speed gates and ticket sales area are vandalised
		Electrical cables and kiosk stripped
Loftus Versfeld Station		

		External painting and platform worn out, painting and resurfacing required
		Existing doors, walls and counters are vandalised
Walker Station		

		Existing structures are vandalised
		Platforms and commuter shelters are damaged
Mears Station		



Water flooding at the ablution area and commuter shelters need to be refurbished



Painting worn out and paving need to be refurbished

Rissik Station