CTROM AVC Accuracy Summary Report

Plaza(s) (Leandra, Leandra Remote Ramps); Date/Hour (01/06/2026 0 - 30/06/2026 23) ,SVC,Adjusted for Lifted Axles and Tailgating

Data for the selected period is consistent

	Class 1		Class 2		Class 3		Class 4		Total Accuracy		Total Vehicles	NC AVC	UC AVC	Total Class Error	Total Error
Lane Id	**Actual**	**Adjusted**	**Actual**	**Adjusted**	**Actual**	**Adjusted**	**Actual**	**Adjusted**	**Actual**	**Adjusted**					
Leandra															
01ME	99.66%	99.77%	83.38%	84.54%	89.55%	90.84%	96.31%	96.55%	97.14%	97.27%	21089	0.00%	0.00%	2.85%	2.86%
02ME	99.69%	99.80%	95.18%	96.53%	67.61%	69.18%	99.27%	99.61%	98.30%	98.44%	18135	0.00%	0.00%	1.70%	1.70%
03ME	99.92%	99.99%	91.49%	92.62%	94.39%	95.89%	98.93%	99.21%	99.39%	99.49%	38266	0.00%	0.00%	0.61%	0.61%
04ME	99.91%	99.98%	92.39%	93.90%	93.88%	96.62%	98.57%	99.17%	99.66%	99.76%	34504	0.04%	0.00%	0.30%	0.34%
05MW	99.83%	99.89%	94.47%	95.84%	95.45%	98.04%	98.34%	98.97%	99.65%	99.74%	44299	0.01%	0.00%	0.33%	0.35%
06MW	99.79%	99.87%	88.55%	89.78%	64.69%	66.27%	91.22%	91.60%	97.59%	97.71%	26101	0.05%	0.00%	2.35%	2.41%
07MW	99.85%	99.93%	94.37%	95.27%	91.26%	92.30%	98.91%	99.09%	98.91%	99.01%	37346	0.00%	0.00%	1.09%	1.09%
Total	99.84%	99.87%	91.41%	91.86%	85.09%	85.66%	97.69%	97.80%	98.89%	98.93%	219740	0.02%	0.00%	1.10%	1.11%
Leandra Remote Ramps															
71RE	99.75%	99.88%	84.35%	86.08%	92.86%	94.77%	99.06%	99.55%	98.57%	98.75%	11294	0.18%	0.00%	1.25%	1.43%
71RW	99.94%	100.00%	92.94%	94.83%	92.74%	94.60%	98.53%	99.02%	99.13%	99.32%	10929	0.00%	0.00%	0.87%	0.87%
72RE	100.00%	100.00%	0.00%	10.68%	0.00%	19.20%	2.78%	6.03%	78.68%	79.89%	258	0.00%	0.00%	21.32%	21.32%
72RW	99.18%	99.68%	93.33%	99.70%	87.18%	93.33%	99.14%	100.00%	98.27%	98.95%	811	0.00%	0.00%	1.73%	1.73%
Total	99.82%	99.91%	87.27%	88.51%	92.12%	93.42%	97.77%	98.11%	98.60%	98.73%	23292	0.09%	0.00%	1.31%	1.40%

Lifted Axles & Tailgating per lane

Mass and Axle Errors per Lane

Lane Id	-Mass Count	-Mass %	+Mass Count	+Mass %	-Axle Count	-Axle %	+Axle Count	+Axle %	NC Count	NC %	Tot Error%

If both Axle and Mass faults occur in the same transaction, both faults will be included in the counts and total of the error table.

Simulated AVC traffic not included in Total Vechile Count

Lane Id	-Mass Count	-Mass %	+Mass Count	+Mass %	-Axle Count	-Axle %	+Axle Count	+Axle %	NC Count	NC %	Tot Error%
Leandra											
01ME	429	2.03%	41	0.19%	323	1.53%	51	0.24%	1	0.00%	4.01%
02ME	63	0.35%	41	0.23%	53	0.29%	190	1.05%	0	0.00%	1.91%
03ME	119	0.31%	24	0.06%	75	0.20%	38	0.10%	0	0.00%	0.67%
04ME	60	0.17%	18	0.05%	24	0.07%	9	0.03%	14	0.04%	0.36%
05MW	45	0.10%	67	0.15%	23	0.05%	30	0.07%	6	0.01%	0.39%
06MW	469	1.80%	36	0.14%	376	1.44%	90	0.34%	14	0.05%	3.77%
07MW	150	0.40%	34	0.09%	204	0.55%	90	0.24%	0	0.00%	1.28%
Total	1335	0.61%	261	0.12%	1078	0.49%	498	0.23%	35	0.02%	1.46%
Leandra Remote Ramps											
71RE	101	0.89%	6	0.05%	39	0.35%	5	0.04%	20	0.18%	1.51%
71RW	46	0.42%	5	0.05%	52	0.48%	4	0.04%	0	0.00%	0.98%
72RE	55	21.32%	0	0.00%	39	15.12%	0	0.00%	0	0.00%	36.43%
72RW	2	0.25%	5	0.62%	5	0.62%	2	0.25%	0	0.00%	1.73%
Total	204	0.88%	16	0.07%	135	0.58%	11	0.05%	20	0.09%	1.66%

If both Axle and Mass faults occur in the same transaction, both faults will be included in the counts and total of the error table.

Simulated AVC traffic not included in Total Vechile Count