

TRANSNET NATIONAL PORTS AUTHORITY

TENDER NUMBER: TNPA/2023/07/0010/36367/RFP

DESCRIPTION OF THE WORKS: FOR THE REPAIR OF OUTER CAISSON SEALING FACE AND CORROSION PROTECTION IN THE PORT OF DURBAN FOR A PERIOD OF THREE (3) MONTHS

CLARIFICATION 001

THE REPAIR OF OUTER CAISSON SEALING FACE AND CORROSION PROTECTION IN THE PORT OF DURBAN FOR A PERIOD OF THREE (3) MONTHS - TNPA/2023/07/0010/36367/RFP

Please see below Clarification to questions that have been received thus far:

- 1) **Q:** Information is required regarding the dimensions of the greenheart timber that will be supplied by TNPA
A: The standard dimensions of the greenheart timber are 500 x 500mm with lengths up to 22m (not necessarily the lengths in our inventory)
- 2) **Q:** Drawings of the greenheart timber are required to determine what machining will be required
A: Drawings cannot be disclosed due to the nature of sensitive design information of the asset involved
- 3) **Q:** Sealing rubbers - Drawings, layout, rubber type and hardness to assist the manufacturer with accurately costing what is required
A: The sealing rubbers are hydraulic gate seal rubbers of the center bulb profile, standards with a typical hardness (IRHD) of around 65 ± 5 , the seal should be able to withstand sea water conditions
- 4) **Q:** Can a site visit be organised for those who wish to view again?
A: Site walk scheduled for Thursday 11 January 2024 at 10h00 (Meet with Wandile Dlamini) at B4/65 Drydock Complex, Entrance A