



Tightness Control System

O R Tambo International Airport

Tightness Test Report

PS procedure at 27-02-2026 03:38:26 AM

Section	Status	Volume [m³]	Tolerable leakrate [l / h]	Measured leakrate [l / h]
S_01	OK	253,35	10,13	-2,34
S_02	Not tested			
S_03	OK	150,25	6,01	-0,77
S_04	OK	43,48	1,74	-0,46
S_05	OK	61,98	2,48	-0,79
S_06	OK	48,31	1,93	0,01
S_07	OK	112,42	4,50	-0,97
S_08	Leak alarm	41,36	1,65	3,88
S_09	Leak alarm	55,39	2,22	4,59
S_10	Error	149,89		
S_11	Not tested			
S_12	Not tested			
S_13	Not tested			

Keenen Stanley PC&IT

Operator

Supervisor

Remarks: