



BID CLARIFICATION

Form No: RW SCM 00041 F

Revision: 02

Effective Date: February 2020

Bid Number RW10384657/22R
Clarification Number 01

Enquiries: Tshepo Morare
Direct Line: Please direct all queries via
e-mail
E-mail: tmore@randwater.co.za
Date: 28 October 2022

BID NUMBER RW10384657/22R – DESIGN, MANUFACTURE, SUPPLY, DELIVERY, INSTALLATION, COMMISSIONING AND PUTTING INTO SERVICE OF AN ELECTRICAL & SMALL POWER AND LIGHTING INSTALLATION AND ASSOCIATED WORKS AT THE VEREENIGING CATHEDRAL HEADER AND ENGINE ROOM 4 VALVE ISOLATION CHAMBERS AT VEREENIGING PUMPING STATION.

Clarity to questions raised

The pages referenced are the pages of the RW10384657/22R bid document.

This clarification consists of 06 statements in the following pages.

SIGNATURES

Tshepo Morare
Buyer

Jabulile Molema
Sourcing Manager

Supply Chain Manager

Clarification questions	Responses
<p>1.We note that the BOQ's provided differ in structure and content (Annexure C2.2 PDF) and the Excel (P.03341 CATHEDRAL HEADER Combined BOQ.xls), please could you clarify which one we should price and return (should it be the pdf, then could we please receive this in native format).</p>	<p>Rand Water retracts the PDF BOQ. Bidders should only complete the Ms Excel (Spreadsheet) BOQ.</p>
<p>2.Furthermore at the Site viewing (18/10/2022), we were advised that the pipe specials (Tee pieces) were being free-issued, could you clarify if these are already completely fabricated and coated? also does this mean that all material as per drawing RA 17924 REV3 is part of that free-issue?</p>	<p>Only the valves and the dismantling joints will be free issued, the valves however need to be refurbished before use. Pipe Specials must be manufactured by the tenderers complete with lining and coating.</p>
<p>3.Are the bolts and gaskets also free-issue?</p>	<p>Only the valves are free issue and are required to be refurbished prior to installation. As per Mechanical BOQ new bolts gaskets and fittings required to complete the installation shall be required.</p>
<p>4.We note that we are to align with the RWB Construction programme, however this has not been included in the documents provided, please could you issue this.</p>	<p>The contractor will be expected to produce a construction program with detailed construction sequencing guided by SS 2.2.6.1 of the project specification.</p>



BID CLARIFICATION

Form No: RW SCM 00041 F

Revision: 02

Effective Date: February 2020

5.Drawing A-9548 Rev 2 Insulation Flanges (4).pdf does not have the dimensions for the 1600 and 2500mm flanges.	A way forward will be given by the 4 th of November 2022.
6.At the meeting, we requested that the presentation that was shared also be distributed, please could you issue this.	The presentation shall not be regarded as the project SOW.