

Date: 24 August 2026

Enquiries:

Tel +27 53 830 5922

MokalaK@eskom.co.za

Dear Tenderers

QUESTIONS AND ANSWERS FOR THE PROVISION OF CORE TECHNICAL SERVICES (ELECTRICAL BUILDING MAINTENANCE SERVICES) TO PROPERTY MANAGEMENT FACILITIES AT HIGHVELD IN PROPERTY MANAGEMENT MPUMALANGA OPERATING UNIT ON AN “AS AND WHEN REQUIRED BASIS” FOR A PERIOD OF FIVE (05) YEARS.

1. Please take note of the following questions that were made in Enquiry No: **E3059DXMPOUR**

Technical criteria feedback:

Questions:


1. for the installation electricians is it a wiremans license that is required or trade test with wiremans?
2. For Electrical Supervisor, please advise if National Diploma in Electrical Engineering can be accepted in place of trade test?
3. Why does Eskom require contractors performing electrical installation work to have ECSA registration instead of, DoEL Electrical Contractor registration? ECSA regulates engineering professionals but it is a private entity, whereas the Electrical Installation Regulations require persons performing electrical installation work as electrical contractors to be registered with DoEL accordingly. What is the legislative basis for making ECSA registration a mandatory tender requirement for this category of work?
4. Most of these rental companies refuse to give us letters of intent. How do we go about that?

Answers:

1. Trade test with wireman's
2. Not accepted, The Electrical Supervisor must have a trade test
3. ECSA registration is not required, valid Registration Certificate either ECA/CEA (SA) (Certificate /proof of application) is required.
4. Unfortunately, we cannot advise on that, you as the service provider must ensure that you meet the requirements.

NOTE: No late tender submission will be accepted.

Yours faithfully,



Nelly Nkosi
Procurement Manager (Limlanga Cluster- Mpumalanga)

GROUP COMMERCIAL

Tactical Procurement: Mpumalanga Operating Unit
Megawatt Park No. 01 Maxwell Drive, Sunninghill
Tel +27 11 709 3743

Eskom Holdings SOC Ltd Reg No 2002/015527/30