



Tightness Control System

## O R Tambo International Airport

# Tightness Test Report

**PS procedure at 20-01-2026 03:40:04 AM**

Section	Status	Volume [m <sup>3</sup> ]	Tolerable leakrate [l / h]	Measured leakrate [l / h]
S_01	OK	253,35	10,13	5,07
S_02	Not tested			
S_03	Not tested			
S_04	Error	43,48	1,74	-1,91
S_05	OK	61,98	2,48	0,34
S_06	OK	48,31	1,93	-0,55
S_07	OK	112,42	4,50	0,62
S_08	OK	41,36	1,65	0,54
S_09	OK	55,39	2,22	-0,61
S_10	Not tested			
S_11	Not tested			
S_12	Not tested			
S_13	Not tested			

Keenen Stanley PC&IT

Operator

Supervisor

Remarks: