



Tightness Control System

## O R Tambo International Airport

# Tightness Test Report

PS procedure at 03-03-2026 04:01:17 AM

Section	Status	Volume [m <sup>3</sup> ]	Tolerable leakrate [l / h]	Measured leakrate [l / h]
S_01	OK	253,35	10,13	-3,48
S_02	Not tested			
S_03	OK	150,25	6,01	1,33
S_04	OK	43,48	1,74	0,53
S_05	OK	61,98	2,48	0,54
S_06	OK	48,31	1,93	0,26
S_07	OK	112,42	4,50	0,23
S_08	Leak alarm	41,36	1,65	2,74
S_09	Leak alarm	55,39	2,22	3,91
S_10	Error	149,89		
S_11	Not tested			
S_12	Not tested			
S_13	Not tested			

Keenen Stanley PC&IT

Operator

Supervisor

Remarks: