


CLARIFICATION 01

TNPA/2026/04/0830/4703/RFQ – THE MAINTENANCE OF BLUFF RADAR TOWER IN THE PORT OF DURBAN FOR A PERIOD OF THREE (3) MONTHS

QUESTION	ANSWER
Please confirm specific paint product and DFT requirements as the document in section C3 Scope of Work pages 4 of 34 and 5 of 34 does not provide the information required.	There is no specific paint, however the required paint needs to comply with ISO 12944:2018, Harbour/Port structures, steel members fall under corrosivity category C5. The DFT requirements for each layer, are specified at part C3: Scope of work under 1.2.2 BLASTING, DERUSTING AND PAINTING STEEL MEMBERS (page 5 of 34).


Hlengiwe Dlamini (Contract Specialist)
Transnet National Ports Authority


Mpendulo Jama (Project Manager)
Transnet National Ports Authority

Transnet SOC Ltd
Registration Number
1990/000900/30

96 Rissik Street
Braamfontein
Johannesburg
Gauteng
2017

P.O. Box 72501
Parkview, Johannesburg
South Africa, 2122

Directors: A Sangqu (Chairperson) R Buthelezi M Debel B Jiya L Letsoalo KG Mbonambi FS Mufamadi D Patel B Sedupane MP Zambane
M Phillips* (Group Chief Executive) N Maphumulo* (Group Chief Financial Officer)
*Executive

Group Company Secretary: Ms S Bopape

www.transnet.net

"This letterhead contains personal information as defined in the **Protection of Personal Information Act, No. 4 of 2013** (the "Act"). The signatory consents to the processing of his/ her personal information and is obliged to handle other data subject's information in accordance with the requirements of the Act".

