


A320 interior inspection

Business Class

- Cabin is showing a lot of wear and tear.
- Seat leathers would ideally need to be replaced
- Plastics are damaged or have hair cracks
- Tray table missing: long leadtime item
- Dent on armrest showing metal (banging of the bottom of tray table on the armrest)
- Damage to consoles









Traytable missing



Damage to armrest



Damage of leather centre consoles:



Plastic buffer underneath traytable hinge has eroded, causing damage to the metal part





Leather covers are worn:



Lifejacket stowage not closing



Damage to paint



Damage to plastics





Economy Class

- Leather seat covers







Paint work and dents





Cracked plastics



Torn leather and damaged steel





