

ANNEXURE A: PICTORIALS




Speed gates, ticket sales area and carports are vandalised



Underground services and paving have been vandalised

Centurion Station



Building needs painting and floor tiles need to be refurbished



Underground services have been vandalized and platform needs resurfacing

Irene Station



Site clearance and fencing need to be done at the station



Commuter shelters and bridge need to be refurbished

Pinedene Station