

Supply Chain Management

REQUEST FOR QUOTES (RFQ)

Description of Goods/ Service required	Differences Training B737-800	
SPECIFICATIONS/ DISCRIPTION		
ITEM/ SERVICE		QUANTITY
Ms. Amina Moola is required to do Boeing 737- 800 differences training from the Boeing 737- 300/400/500 type for revalidation of her ATPL license as a P1. Her 36-month expiry is the end of July 2023, so the training needs to be complete before then. The training should include a pilot to man the simulator with her during her training.		1
It should include a technical refresher and PBN/ RNP ground and		
simulator training		
		N. A.
GENERAL/ COMMENTS: Urgency is requested as inspector qualification on type is		
Incumbent for the coverage of SACAA Inspector Licenses		
Incumpent for the coverage of OAOA (mapostor Electron)		
		1 to 1 to 2 to 2 to 2 to 2 to 2 to 2 to