

Invitation to tender DHP, DCP & ACP			
Functionality Requirements	Criteria	Weight	Company
Mandatory	Previous or current orders with Contract value between R60M and R100M (Ref letter or copy of contract with contact details for the employer as proof)	YES/NO	
	Supplier key personnel – Site Manager and Supervisor must have 3 years experience DUST AND ASH PLANT maintenance management. Provide Reference letter	YES/NO	
Company Experience	Related Company Experience in Dust or Ash Maintenance 3 Years or more experience 30% 2-3 years experience 20% 1-2 Years experience 10% Provide proof that company has 3 years related experience	30%	30%
Management Experience	Related Personnel Experience and qualifications:	30%	
	Site Supervisor/Project Manager N6 Technical Diploma/S4 plus 3years related experience (Supervisory) - 10% Supervisory/Management training (MDP, TSP, SDP, Project Management, etc) - 10% Attach proof (both their CVPs and qualifications)	20%	10%
Maintenance Experience	Related Personnel Experience and qualifications:	40%	
	Provide all the isolations points required by PLANT SAFETY REGULATIONS before work can proceed inside an Ash Silo	25%	
	Mention all the documents required before entering the Ash Silo in terms of plant safety regulations eg. PERMIT TO WORK	25%	25%
	Threshold is 80%	100%	65%
Outcome	The minimum weighted final score (threshold) required for a tender to be considered from a technical perspective is 80%. Should no Contractor meet the minimum threshold of 80% Eskom reserves the right to negotiate and/or consider Contractors that obtained 75%.		