

ATTACHMENT PICTURES:



**OLD ENGINE & PUMP SET**



**70 YEAR OLD ENGINE**



**#2 ENGINE CRACKED SUMP**



**#5 ENGINE NO COMPRESSION**



**TYPICAL PUMP LEAKS**



**TYPICAL INSIDE OF PUMP BEFORE REFURB**



**NEW ENGINE PUMPSET DELIVERING REQUIRED FLOW**

