



**Quotation for the installation of air cons at
Durmain server room**

SCOPE OF SUPPLY AND SPECIFIC INSTRUCTIONS

Legislative Requirements

The service provider will be responsible for the provision of required service as described in specification below. All services including materials and workmanship to be in accordance with these specification guideline and client requirements, applicable to local and national building regulations and industry standards for respective trades.

The workmanship under this contract shall be in line with S.A.B.S standards and the Occupational Health and Safety Act, Act No. 85 of 1993, as amended. the Compensation for Occupational Injuries and Diseases Act and Environmental Acts

PPE (Personal Protective Equipment)

All PPE needed must be supplied by the service provider

All PPE are to conform to the requirement as prescribed by Department of Health (DOH)

Security and Employment Vetting

The bidder's personnel, who render services at SAPO sensitive security areas, must, at the cost of the bidder, be cleared up to the level of "CONFIDENTIAL" by SAPO.

The bidder is required as a minimum to conduct employment, vetting and security checks of all employees deployed to SAPO's service areas. Failure comply will result in breach of contract conditions.

Personnel must be clearly identifiable via uniforms and security identification cards.

The service provider will be subjected to a security screening process in line with SAPO prescribed processes.

DESCRIPTION OF SERVICE

Appoint a service provider for the supply of materials and labour to Install Air conditioning at

Durban Regional office, 290 Dr Pixley Kaseme, Durban.

SPECIFICATIONS

Note: descriptions below are indicative of the work required to be executed on site. It is the responsibility of the bidders to allow in pricing for all necessary works, equipment and material required for the successful completion of the project as intended by SAPO.

All requirement data and details to be confirmed on site prior to submission of pricing SAPO.

No additional cost will be entertained.



	Installation of two under ceiling Air con in Durmain Server Room		Site Name		Server room
Item	Description		UOM	Quantity	Rate
					Total
1	Installation of a 32000 BTU invertor Cerrier Under ceiling air con units	each		2	
2	Allow for flushing out existing copper pipe and connect existing copper pipe to one new units, pipe up,	item		1	
3	Allow for the supply and installation of new pipes and electrical connection	item		1	
4	Removal and disposal of the damaged out door unit	each		1	
5	Disconnection and disposal of the non functioning indoor unit	each		1	
6	New air con unit to be connected to the existing electrical supply(supplying disconnected units)	each		2	
NB	Air cons will be supplied by SAPO		VAT		
			TOTAL		

Approved;
Jabulani Kubheka
2023-03-06