

**Extreme License Renewal 2022/23**

Product	Part #	Service Product Type	Service Part #	Serial Number	End Date	Quantity	Service Class
8404C CHASSIS 4 SLOTS	EC84000X2-E6	PW NBD AHR H34092	95504-H34092	18JP3420CR1P	31-Jul-2022	1	Hardware
8404C CHASSIS 4 SLOTS 1 AC PS NO PC	EC8400A02-E6	PW NBD AHR H34092	95504-H34092	15JP315C600R	31-Jul-2022	1	Hardware
8404C CHASSIS 4 SLOTS 1 AC PS NO PC	EC8400A02-E6	PW NBD AHR H34092	95504-H34092	15JP383C6011	31-Jul-2022	1	Hardware
8404C CHASSIS 4 SLOTS 1 AC PS NO PC	EC8400A02-E6	PW NBD AHR H34092	95504-H34092	15JP383C601N	31-Jul-2022	1	Hardware
8418XSQ 16x1/10G SFP+2x40G QSFP+GSA	EC8404005-E6GS	PW NBD AHR H34101	95504-H34101	15JP244CD025	31-Jul-2022	1	Hardware
8418XSQ 16x1/10G SFP+2x40G QSFP+GSA	EC8404005-E6GS	PW NBD AHR H34101	95504-H34101	15JP244CD03T	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	15JP244CD020	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	15JP244CD022	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	18JP3430CD25	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	18JP3430CD20	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	18JP3430CD2L	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	18JP3430CD0H	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	18JP3430CD0C	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	18JP3430CD0N	31-Jul-2022	1	Hardware
8418XSQESM 16x1/10G SFP+2x40G QSFP+	EC8404005-E6	PW NBD AHR H34100	95504-H34100	18JP3430CD1E	31-Jul-2022	1	Hardware

