



**SPECIFICATION
FOR
CUTTING OF TRESS, REMOVING FALLEN AND UPROOTED TREES, VEGETATION CONTROL
AT
VREDENBURG CAMPUS**

*Private Bag X5017,
Stellenbosch, 7599
Cape town
Tel: (021) 887 5090*

Email: mashininin@arc.agric.za



CAMPUS
SERVICE

: VREDENBURG CAMPUS
: CUTTING OF TREES, REMOVING UPROOTED TREES, VEGETATION
CONTROL

1. SCOPE OF WORK

- Cut **all** the trees that have fallen over the perimeter fence posing a risk to the security personnel preventing them to do their security rounds.
- **Prune** the trees and cut out dead branches.
- **Remove** trees that have fallen due to heavy winds.
- **Remove huge** tree stems around the campus
- **Remove** trees that are uprooted.
- Remove trees have over lapped the parameter fence.
- Remove dead tree branches.
- Removing weeds using parameter fence as their base structure
- The work to be done on site requires a trained operator.
- The service provider must have heavy-duty equipment and skills to cut out big trees.
- The service provider shall dump all **materials** collected for removal, in a legal manner.

2. BILLS OF QUANTITIES

Item Description	Quantity		Rate	Total
Cut ALL the tress that have falling and over the perimeter fence	TBC			
Prune the trees and cut out dead branches.	TBC			
Remove trees that have fallen, remove trees that are uprooted, Remove trees have fall over lapping the parameter fence, Remove dead tree branches	TBC			
Removing weeds using parameter fence as their base structure	TBC			
All materials collected for removal, shall be dumped by the service provider in a legal manner	sum			
Labour and travelling	sum			
			Sub-total	
			VAT @ 15%	
			Total	

3. GENERAL

- TBC- To Be Confirmed during site meeting
- Please report to the reception for access certificate before you can commence any work on the campus.
- ARC will supply no tools or workmanship.
- Any damages caused to the building or anything in the premises during this project must be repaired.
- The site must be left clean and tidy after completion of the project.
- The service provider shall provide own equipment, vehicles, machinery, rakes, spades workers etc.
- The service provider must make use of **CORRECT** Personal Protective Equipment
- Site assessment is very vital before work commences
- Any challenges hindering the service provider to the job must be communicate prior
- All workers must adhere to the **Occupational Health and Safety Act (Act 85 of 1993)**
- The service provider shall comply with **The Basic Conditions of Employment Act (Act 75 of 1997)**
- Chemicals used must be non-hazardous to animals, and people and used according to manufactures instructions and also must be very careful when using the chemicals since **ARC is a research facility for plant pathology.**
- All work must be done during office hours from 08h00 – 15h30 (unless by pre arrangement with the facility manager at telephone number 021 887 5090 during office hours.)