



PetroSA

The Petroleum
Oil and Gas Corporation
of South Africa (Pty) Ltd
Reg. No. 1970/008130/07
151 Frans Conradie Road,
Barrow, 7500

Note: All tenders and quotations are done via our eProcurement system.

The information given below is an extract of the scope of work. **To access/open the full set of tender documentation, you must be registered on CSD.**

If you have a MAAA CSD registration number and receiving email notifications from PetroSA Procurement you are already registered, please login as indicated below:

Username: MAAA...
User Code: MAAA...
Password: newuser

Contact the call center on **012 663 8815** or email: **support@intenda.net** if you are having problems with your login.

If **you do not have a MAAA** CSD registration number, please click on “**Not Registered Yet**” and register. Click on the link below to download a “how to” guide to assist you.

<http://www.procurement.petrosa.com/Downloads/Documents/SupplierSelfRegistration.pdf>

SCOPE OF WORK

ENQUIRY NO: AHT0000026479

**DESCRIPTION: MAINTENANCE OF CARBON DIOXIDE FIRE EXTINGUISHERS
FOR PetroSA, MOSSEL BAY**

1. INTRODUCTION

2. SCOPE OF SERVICES

2.1 HYDROTESTING OF CARBON DIOXIDE FIRE EXTINGUISHERS

PetroSA utilizes high-pressure carbon dioxide fire extinguishers in some of its facilities. It is a legal requirement under SANS 1475 Part 1-2010 (Service and Maintenance of Portable and Mobile Fire Extinguishers) that fire extinguishers be visually inspected every 12 months, pressure tested and refilled by a qualified and certified SAQCC Practitioner. These cylinders (CO₂) must be hydrostatically tested every ten years at SANAS approved testing station.

The Supplier will be required to perform the following services for PetroSA.

2.2 Hydrostatic testing of Carbon Dioxide fire extinguishers:

- a) Hydrostatic test of the fire extinguisher
- b) Visual inspection of the unit (inside and outside)
- c) Leak test
- d) Inspect the valve assembly for defects
- e) Inspect the cylinder neck assembly (treads) for defects
- f) Pressure test stickers/stamping/pressure test neck ring signed off
- g) Provide the pressure test certificates
- h) Replacement of defective seals
- i) Repainting of 5kg extinguishers shell – ensure equipment identification numbers are legible (Mossel Bay Facility extinguishers)
- j) Delivery of the fire extinguishers to/from Cape Town PetroSA facility – (65) (as per CBA)
- k) Delivery of the fire extinguishers to/from Mossel Bay PetroSA facility – (287) (as per CBA)

3. CHANGES TO THE SCOPE OF SERVICES

The scope of the Services shall be subject to changes by additions, deletions, or revisions thereto by PetroSA. The Supplier shall be advised of any such changes by written notification from PetroSA describing the change. The Supplier shall promptly perform and strictly comply with each such change when so instructed by PetroSA. Any extra services resulting from such changes will be charged at the Supplier's normal or agreed rates.

4. ENQUIRIES

Any enquiries regarding this tender should be addressed to **Banzi Dlamini** in the Tender Office at telephone no. **+27 44 601 2311**, or e-mail address **Banzi.dlamini@petrosa.co.za**.