

FOSKOR FLEET SERIAL NUMBERS

FOSKOR		
MACHINE MODEL	FLEET NUMBER	SERIAL NUMBER
730E	10006060 9568	A30120
730E	10006061 9574	A30257
730E	10006062 9575	A30260
730E	10006063 9576	A30279
730E	10006064 9577	A30280
730E	10006839 9578	A30576
730E	10006840 9579	A30577
730E	10006841 9580	A30578
730E	10006842 9581	A30579
730E	10010205 9586	A30648
730E	10010204 9587	A30649
730E	10015474 9591	A30681
730E	10015475 9592	A30682
730E	10015476 9593	A30683
HD785-7	10009439 9583	9575
HD785-7	10009246 9584	9424
HD785-7	10010030 9588	N10484
HD785-7	10010031 9589	N10486

FOSKOR		
MACHINE MODEL	FLEET NUMBER	SERIAL NUMBER
WA430-5	10006777 0902	61250
WA430-5	10006778 0903	61252
WA430-6	10017133 1905	66563
WA430-6	10017134 1906	66564
GD655-3	10006775 0901	11344
WD600-6	10014336 1605	55068
D375-5	10006071 702	18786
D375-5	10008072 709	18924
D375-5	10004820 1203	18939
D375A-6	10008447 1002	60055
WA1200-3	10006075 2034	50060
WA1200-6	10017773 2036	60075
PC5500	10006073 2033	15016
PC5500	10006074 2035	15059
WA800-3EO	10009289 9585	70051
WA800-3EO	10010435 9590	70062
GD675-5	10015114 1701	56164
GD825A-2	10016453 1802	13120
PC300-8	10016806 1807	64619

Annexure C

tsu

FOPS CERTIFICATION

This protective structure was provided to comply with the following standard.

FOPS: ISO 3449 : 2005

MODEL

SERIAL No.

6DB311-6
24F7755

MACHINE MODEL

FOPS LEVEL No.

- If any modification is applied to the FOPS, it may affect the strength and may not comply with the standard. Do not drill, cut or weld on the FOPS structure. Any modification is prohibited.
 - FOPS may provide less protection if it has been structurally damaged.
- Consult Komatsu Distributor in that case.

Komatsu Ltd. 2-3-6 Akasaka, Minato-ku, Tokyo, Japan

09620-C2171
09620-C2001

KOMATSU

FOPS CERTIFICATION

This protective structure was provided to comply with the following standard.

FOPS: ISO 3449 : 2005

MODEL

SERIAL NO.

MACHINE MODEL

FOPS LEVEL NO.

WARNING

- If any modification is applied to the FOPS, it may affect the strength and may not comply with the standard. Do not drill, cut or weld on the FOPS structure. Any modification is prohibited.
 - FOPS may provide less protection if it has been structurally damaged.
- Consult Komatsu Distributor in that case.

09620-C2171

09626-C2001

Komatsu Ltd.

2-3-6 Akasaka, Minato-ku, Tokyo, Japan

ANNECTURE II

MODEL

GD955-7R

SERIAL No.

50023

Product Identification Number

KMTGD038VRD050023

MANUFACTURER

Komatsu Ltd., Tokyo, Japan

KOMATSU

03512-10002

