SCHEDULE OF DRAWINGS: Rev0

<u>Nr.</u>	<u>Drawing Nr.</u>	<u>Drawing Title / Information</u>	Rev
1	CSE 1C 108: sht. Q000	Hazendal equipment/SER layout	0.3
2	CSE 1C 108: sht. P001	Hazendal Single line diagram (Power Architecture)	0.3
3	CSE 1C 108: sht. P013	Hazendal UPS Layout	0.3
4	CSE 1C 108: sht. P014	Hazendal UPS I/O and UPS equipment layout	0.3
5	CSE 1C 108: sht. P015	Hazendal UPS analysis	0.3
6	CSE 1C 122: sht. Q000	Retreat equipment/SER layout	0.1
7	CSE 1C 122: sht. P001	Retreat Single line diagram (Power Architecture)	0.3
8	CSE 1C 122: sht. P013	Retreat UPS Layout	0.3
9	CSE 1C 122: sht. P014	Retreat UPS I/O and UPS equipment layout	0.3
10	CSE 1C 122: sht. P015	Retreat UPS analysis	0.3
11	CSE 1C 127: sht. Q002	Simonstown equipment/AR layout	0.1
12	CSE 1C 127: sht. P001	Simonstown Single line diagram (Power Architecture)	0.1
13	CSE 1C 127: sht. P013	Simonstown UPS Layout	0.1
14	CSE 1C 127: sht. P014	Simonstown UPS I/O and UPS equipment layout	0.1
15	CSE 1C 127: sht. P015	Simonstown UPS analysis	0.1