

Customer : ARMSCOR DOCKYARD
 Contact Person : A. NGOBELI
 Tel. No. : 021 787 3872
 Vessel/ Unit : WASTE YARD

Enquiries : Mrs R Mnisi
 Tel No. : 021 787 3199
 Fax No. : 021 787 3144
 E-mail : RefilweM1@armscordy.co.za

Certificate of Analysis


(Bilge Water Results)

Date Sampled: 27/08/2025	Date Received : 27/08/2025
Job Card No.:	Date Started : 01/08/2025
SP No.:	Sample No. : 08/182
Sample ID: WASTE YARD BOWSER	

Parameters	Test Results
pH	6.97
Electrical Conductivity (mS/m)	0.43
Chemical Oxygen Demand (mg/l)	13 360
Total Dissolved Solids (mg/l) Calculated	2.76
Appearance	Dirty
Visual Inspection	Grey liquid with particles.

COMMENTS:

- The pH of the sample is neutral. The COD is very high indicating that the sample is highly contaminated with inorganic and organic pollutants.
- It is recommended that the safety data sheet be provided if applicable.

_____ Analysed by: Ms. U Luvhengo Date Completed: 01/09/2025	 _____ Approved by: Ms. R Mnisi Section Manager CBM	Date: 01/09/2025
--	---	-------------------------

Notes:

1. The results reported relate only to those items listed.
2. The quality and integrity of the samples submitted has a direct correlation on the results reported. Results reflected on this report therefore, relate only to the sample as received.