


Annexure B: Stations Current or Vandalism Pictures

Springs.





Vandalized toilet facilities.

- Commuters waiting shelters Type 2 (Including toilet facilities).





Pollak Park.





Vandalised building.







Vandalised building.



ties.




- Commuters Waiting Shelters (Platform canopies).





New Era.








Vandalised building.














Vandalised shelters.



















Schapenrust.













Brakpan.



Aging building but in fairly good condition.





Aging building. Rust on garage steel doors, and paint peeling off walls.




Aging building. Paint peeling off walls.





Anzac.




Apex.






Vandalized building.







- Unmarked Building 2.







- Toilet Blocks.






Vandalized toilet facilities.

- Commuters Waiting Shelters (Platform canopies).



Vandalised and burned shelters.

Commuters Gates (Entrance/Exit).



New Kleinfontein.



Benoni.



Vandalized building.


















Boksburg East.



Burned building.



Boksburg.



Building has deteriorated due to aging and vandalism.

- Toilet block and Unmarked building.




Aging Shelters.

East Rand





- Toilet Blocks.





Angelo



Delmore

