Occupational Health and Safety Baseline Risk Assessment Susiness / Operating unit: Drakensberg Pumped Storage Scheme Next Review Date (every 2 years) 01-Mar-24 Template identifier: 240-70044 Date: 01-Mar-22 hillie Mbanjwa, Ritta Zimu, thembile Rahlao, Zandile nukwa, Zama Mkhize, numlani Ntombela, Andre Van onder, Jeff Phungula, Steven alatsi, Kwanele Nkosi, nolisile Mjilo, Sifiso Dlamini, iphamandla Kuenene, Charles Prepared by: Authorised by: Name: Maremane Tsotetsi
Designation: Plant Manager Refer to Occu What are the possible consequences? Activity type (Routine / Non-routine) Where applicable, add IRM system reference number for tracking of treatment actions. Who is accountable for making sure the controls and monitors are:
- in place,
- implemented,
- regularly reviewed for effectiveness. Risk Priority Rating Lkelihood Elimination Substitution Engineering controls Administrative control Personal protective equipment (PPE) Occupational Health and Safety Act, 1993 (Act No. 85 of 1993) Noise Induced Hearing Loss Regulations Falling from the man cage Safety clearance for working at height and use of rope to balance the man and Safety Act, 1993 (Act No. 85 of 1993) GN R1031 -GSR, Occupational Health and Safety Act, 1993 (Act No. 85 of 1993) & Plant Safety Regulations Regulations

Occupational Health
and Safety Act, 1990
(Act No. 85 of 1993. Assistant Bullding
Regulations and
Bulding Regulations and
Bulding Sandards
Act 103 of 1977
Occupational Health
and Safety Act, 1993
National Bulding Sandards
Act 103 of 1977
Occupational Bulding Sandards
Act 103 of 1977
Occupational Feath
Occupational Act 103 of 1973
Occupational Peath
O Non slippery pads installed, cleaning of oil from the stairs, facing the stairs when climbing down, use tool bucket ip and fall Oil spill on the floor mixed wit Construction
Occupational Health
and Safety Act, 1993
(Act No. 85 of 1993 GN R1031 - GSR,
19988 GN R85
Construction Location Control of the Control of t Safety clearance for Working at height Apply three point or safety clearance for working at height Regulation 2014; Driven Machinery and Salety Act, 1993. Act No. 86 of 1993. GN R1031 - GSR 19988. GN R60 Regulation 2014 Cocupational Business Act No. 86 of 1993. All Control Business Cocupational Business Business Salety Act, 1993. Act No. 86 of 1993. All R1031 - GSR 1998 - GN R60 GN emoval and replacement comps for maintenance Apply three point o safety clearance fo working at height Occupational Health and Safety Act, 1903 (Act No. 85 of 1993; GN R84 Construction Regulation 2014; Driven Machinery Occupational Health and Safety Act, 1903 (Act No. 85 of 1993 -National Building Regulations and Building Standards Act 103 of 1977 Apply three point or safety clearance for working at height Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R84 Construction Regulation, 2014; Driven Machinery Regulation, 2015 ruck by, caught between Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 & PSR Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 - National Building Regulations and Building Standards Act 103 of 1977 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 - GN R1031 - GSR
Occupational Health and Safety Act, 2007 Occupational Health Act, 200 Apply three point or safety clearance for working at height OM PETUD 1- CISSE

COURSEINED AND POTENTIAL PROPERTY OF THE PETUD POTENTY O Training, Ladder inspections and safety clearance for working at heights Isolation, test before touch Isolating/de-isolating electrical Basic Conditions of Employment Act & Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R1031 GSR 1986; Facilities Occupational Safety Act, 1993 (Act No. 85 of 1993; GN R1031 General Safety Regulations 1996 Carrying instruments and to hand while using stairs Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 -GN R1031 - GSR, 1996& GN R84 Construction Regulation, 2014 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993) - GN PLOTA CSP Occupational Health and Safety Act, 1993 (Act No. 85 of 1993) - Noise Induced Hearing Loss Regulations Supervisor/ Manager Reguasions

Occupational Health
and Safety Act, 1993
(Act No. 85 of 1993 GN R734 Pressure
Equipment
Remaistron 70/10
Occupational Health
and Safety Act, 1993
(Act No. 85 of 1993 GN R1031 - GSR
1998& GN R85
Construction
Tenulation 2014 ontact with high ressure water Crack on the vessel Gas test to be done before entry and continuously during the task, environmental certificate to be issued. Continuous supervision. Construction Regulation 2014 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993) -GN R1031 -GSR, 1986 rking at height

Welding, cutting, and brazing operations.	N	1	Metal fumes	1	Inhaling fumes	Health	Toxic furnes generated from the activity	None	Employees/ Contractors/ Visitors	Supervisor/ Manager	Weekly, 2hrs	Medical	PPE, barricading, PTW, hot work approval, Use of mobile furnes extraction unit	В	III F	Task specific risk assessment	Behavioural safety observations	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; NEMA: Air Quality Act 39 of 2004; GN R1031 GSR 1986; Environmental Regulations for Workplaces 1987	None	Complete	None
		2	Ultraviolet (UV) radiation	1	Damage eye sight	Health	Exposure to UV light	None	Employees/ Contractors	Supervisor/ Manager	Weekly, 2hrs	Medical	Wearing Welding face 3 shield, barricading	В	III F	Task specific risk assessment	Behavioural safety observations	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R1031 GSR 1986; Environmental Regulations for Workplaces 1987	None	Complete	None
		3	Cutting	1	Burns	Safety	Contact with Hot metal or the cutting torch		Employees/ Contractors	Supervisor/ Manager	Weekly, 2hrs	LTI	Correct use of appropriate 4 PPE for cutting with a cutting torch	В	III F	Task specific risk assessment	Behavioural safety observations	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R1031 GSR 1986; Environmental Regulations for Workplaces 1987	None	Complete I	None
		4	Caught in between and falling objects	1	Crushed toes and fingers	Safety	Incorrect handling of material		Employees/ Contractors	Supervisor/ Manager	Weekly, 2hrs	LTI	Use of correct PPE, Following correct work instruction	В	III F	Task specific risk assessment	Behavioural safety observations	Supervisor/ Manager	Basic Conditions of Employment Act & Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R1031 GSR 1986; Facilities Regulation 2004	None	Complete	None
		5	Sparks	1	Eyes damage and burns	Safety	Flying sparks from welding		Employees/ Contractors	Supervisor/ Manager	Weekly, 2hrs	LTI	Use of correct PPE, Following correct work instructionPTW, hot work approval,	В	III F	Task specific risk assessment	Behavioural safety observations	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R1031 GSR 1988; Environmental Regulations for Workplaces 1987	None	Complete	None
Maintenance of DB's	R	1	Live circuits	1	Electrical shock	Safety	Contact with live circuits	None	Employees	Supervisor/ Manager	Six monthly, 8hrs	LTI	Permit to work, test before 4 touch	В	III F	Task specific risk assessment	Safety behavioural observations	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993	None	Complete I	None
Maintenance of Plugs	N	1	Live circuits	1	Electrical shock	Safety	Contact with live circuits	None	Employees	Supervisor/ Manager	Six monthly, 8hrs	LTI	Permit to work, test before 4 touch	В	III F	Task specific risk assessment	Safety behavioural observations	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993	None	Complete	None
Use of Guillotine	N	1	Sharp edges from metal pieces	1	Cuts	Safety	Sharp edges from the cut metal pieces	None	Employees/ Contractors	Supervisor/ Manager	Quarterly, 4hrs	Medical	PPE, barricading 3	В	III F	Task specific risk assessment	Safety behavioural observations	Supervisor/ Manager	& PSR Occupational Health and Safety Act, 1993 (Act No. 85 of 1993	None	Complete	None
		2	Cutting of the metal	1	Cutting of fingers	Safety	Co-ordination between hands and feet while cutting	None	Employees/ Contractors	Supervisor/ Manager	Quarterly, 4hrs	LTI	PPE, following the correct 4 procedure	В	III F	Task specific risk assessment	Safety behavioural observations	Supervisor/ Manager	&General Machinery Regulation, 1988& Driven Machinery Regulations, 2015 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 &General Machinery Regulation, 1988&	None	Complete	None
Use of the Drilling machine	N	1	Supporting the work piece by hand	d 1	Cuts from a swinging work piece	Safety	Not using a holding clamps	None	Employees/ Contractors	Supervisor/ Manager	Weekly,2hrs	LTI	Wearing of hand gloves 4	В	III F	Use of the clamps or the vice grip, Task specific risk assessment	Safety behavioural observations, inspections	Supervisor/ Manager	Driven Machinery Regulations, 2015 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 &General Machinery	None	Complete	None
		2	Flying metal chips	1	Eye injury	Safety	Not wearing appropriate PPE during the activity	None	Employees/ Contractors	Supervisor/ Manager	Weekly,2hrs	LTI	Wearing of goggles, 4 training	В	ш	Task specific risk assessment	Safety behavioural observations, inspections	Supervisor/ Manager	Regulation, 1988& Driven Machinery Regulations, 2015&Electric Machinery Occupational Health and Safety Act, 1993 (Act No. 85 of 1993	None	Complete I	None
		3	Cleaning metal chips with bare hands	1	Cuts	Safety	Cleaning with a hand instead of brush	None	Employees/ Contractors	Supervisor/ Manager	Weekly,2hrs	Medical	Wearing of hand gloves, 3 training	В	ш ғ	Task specific risk assessment	Safety behavioural observations, inspections	Supervisor/	&General Machinery Regulation, 1988& Driven Machinery Regulations, 2015&Electric Machinery Regulation, 2011	None	Complete	None
Dressing the grinding wheel	R	1	flying particles	1	Injury from flying	Safety	Flying pieces generated from	None	Employees	Supervisor/	Quaterly,1hr	LTI	Wearing of hand gloves 4	В	III F	Task specific risk assessment	Safety behavioural	Manager Supervisor/	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 & General Machinery Regulations, 1988& Driven Machinery Regulations, 2015&Electric Machinery Occupational Health	None	Complete	None
					pieces of grinding stone		dressing the wheel			Manager			and face shield, training				observations, Inspections	Manager	and Safety Act, 1993 (Act No. 85 of 1993 & Driven Machinery Regulations, 2015&Electric Machinery			
Use of the Grinding machine	N	1	Dressing the grinding wheel	1	Injury from flying pieces of grinding stone	Safety	Flying pieces generated from dressing the wheel		Employees	Supervisor/ Manager	Quaterly,1hr	LTI	Wearing of hand gloves and face shield, training	В	III F	Task specific risk assessment	Safety behavioural observations, inspections	Supervisor/ Manager	Regulation, 2011 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 & Driven Machinery Regulations, 2015&Electric Machinery Regulation, 2011	None	Complete	None
		2	Breaking of grinding stone	1	Injury from flying pieces of grinding stone	Safety	Incorrect grinding method	None	Employees/ Contractors	Supervisor/ Manager	Weekly,2hrs	LTI	Grinding wheel to be secured by guards, PPE, training	В	III F	Task specific risk assessment	Safety behavioural observations, inspections	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 & Driven Machinery Regulations, 2015&Electric Machinery	None	Complete	None
	N.	3	Sparks from grinding Contact with the machine while in	1	Eye injury Hand injury	Safety	Flying sparks from grinding Not following the work instruction	None	Employees/	Supervisor/ Manager	Weekly,2hrs Monthly,1hr	Medical	Wearing of goggles 3 Risk assessment and PPE 4	В	III F	Task specific risk assessment Training, To develop a work	Safety behavioural observations	Supervisor/ Manager	Regulation. 2011 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 & Driven Machinery Regulations, Regulations, Machinery Occupational Health	None	Complete	None
Cutting of metal using Power saw.		2	operation Splashing of Cooling fluid	1	Cooling fluid splashing on to the		Not following the work instruction		Contractors Employees/ Contractors	Manager	Monthly, thr	Medical	Risk assessment and PPE 3	В	III F	instruction	observations Safety behavioural observations	Manager Supervisor/ Manager	and Safety Act, 1993 (Act No. 85 of 1993 & Driven Machinery Regulation, 2015&Electric Machinery Remulation 2011 Occupational Health and Safety Act, 1993	None		None
	R	14	Removal and replacement		eyes Tripping and falling	Safety	Poor housekeeping	None	Employees/	Supervisor/	Quarterly, 8hrs	LTI	Ensure good 4	В	III P	To inspect equipment one at a		Supervisor/	(Act No. 85 of 1993 & Driven Machinery Regulations, 2015&Electric Machinery Regulation, 2011	None	Complete	None
Inspection of lifting equipment at. I the sling store						out,	Too reasonage g		Contractors	Manager	edition, and		Ensure good housekeeping, STAR principle, area to be cordoned off, only person involved in the task to be allowed in the area			lime	observations	Manager	and Safety Act, 1993 (Act No. 85 of 1993 - Environmental regulation of Workplaces, 1997&F-colities Regulations, 2004& National Bulding Regulations and Building Standards			
				3	Equipment falling Falling from height	Safety	Incorrect handling,	None Working at heights rescue training	Employees/ Contractors	Manager Supervisor/	Quarterly, 8hrs Quarterly, 8hrs	LTI	PPE 4 Inspection of ladders, 4	В	III P	using of crane for heavy equipment Task specific risk assessment	Behavioural safety observations	Supervisor/ Manager	Aut 109 at 1077 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 - GN R1031 - GSR, 19988 GN R84 Construction Regulation 2014 Occupational Health	None	Complete	None
Removal and stacking of portable.	N	1	Lifting or handling ladders	1	Caught in between	Safety	Improper handling of ladders	None	Contractors Employees/	Manager Supervisor/	Weekly, 8 hrs	Medical	training on using ladders Risk assessment 3	В	III P	OE's	and Behavioural safety observations Behavioural safety	Manager Supervisor/	and Safety Act, 1993 (Act No. 85 of 1993) - GN R1031 -GSR, 1986 Occupational Health	None	Complete	None
Rigging and lifting	N	1	Position signalling by the rigger	1	or struck by falling ladders Inadvertent movement of the load	Safety	Poor coordination between the crane driver and the rigger		Employees/ Contractors	Manager Supervisor/ Manager	Weekly, 4 hrs	Fatality	Training, crane inspections 5	В	II F	Task specific risk assessment, Declaration of fitness	observations, OE records Inspections, training records, OE's and Behavioural safety observations	Manager Supervisor/ Manager	and Safety Act, 1993 (Act No. 85 of 1993 - GN R1031 - GSR, 1996& GN R84 Construction Regulation, 2014 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993)	None	Complete	To be registered on IRM
		2	Poor condition of the lifting equipment	1	Load falling	Safety	Loading equipment failure	None	Employees/ Contractors	Supervisor/ Manager	Weekly, 4 hrs	Fatality	Load testing, Training, inspections, use of correct lifting methods	В	II F	Task specific risk assessment	Inspections, training records, OE's and Behavioural safety observations	Supervisor/ Manager	GN R84 Construction Regulation 2014; Driven Machinery Regulation 2015 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993;	None	Complete	To be registered on IRM
		3	Suspended load	1	Load falling	Safety	Crane failure, load improperly secured	None	Employees/ Contractors/ Visitors	Supervisor/ Manager	Weekly, 8 hrs	Fatality	Load testing of crane, inspections, rigging safety clearance, use of certifed equipment	В	II F	Task specific risk assessment, pre-work inspections	Load testing certificates, rigging safety clearance and inspection records	Supervisor/ Manager	GN R84 Construction Regulation 2014; Driven Machinery Regulation 2015 Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R84	None	Complete	To be registered on IRM
				2	Struck by	Safety	People around the area where crane movement is taking place	None	Employees/ Contractors/ Visitors	Supervisor/ Manager	Weekly, 8 hrs	LTI	Crane driver and the rigger to ensure the area is safe to move the load	В	III F		Safety behavioural observations	Supervisor/ Manager	Construction Regulation 2014; Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R84 Construction Regulation 2014;	None	Complete	None
Spherical Valve 380V Board	R	4	Driver Competency Live circuits	1	Injury Electrical shock	Safety	Key not controlled Contact with live circuits	None	Employees Employees	Supervisor/ Manager Supervisor/ Manager	Daily, 1hr 18 monthly, 8hrs	LTI	Key to be controlled by 4 OPS Permit to work, test before 4 touch, Follow correct	A	III P	book	Monitor key is only issued to authorised craned drivers Safety behavioural observations	Supervisor/ Manager Supervisor/ Manager	Driven Machinery Occupational Health and Safety Act, 1993 (Act No. 85 of 1993; GN R84 Construction Regulation 2014; Act 1903 and Safety Act, 1903	None		None
maintenance		2	Working with electrical cleaner	1	Contact with the chemical	Safety	Chemical splash	None	Employees/ Contractors	Manager Supervisor/ Manager	18 monthly, 8hrs	Medical	touch, Follow correct procedure PPE, following the correct procedure, Consult MSDS	В	III F	Task specific risk assessment	observations Safety behavioural observations	Manager Supervisor/ Manager	(Act No. 85 of 1993 8_PSR Occupational Health and Safety Act, 1993 (Act No. 85 of 1993). National Environmental Management, Air Quality Act 39 of	None	Complete	None
				2	Inhaling fumes	Health	Chemical fumes	None	Employees/ Contractors	Supervisor/ Manager	18 monthly, 8hrs	Medical	Wearing of the respirator, following the correct procedure, Consult MSDS	В	III F	Task specific risk assessment	Safety behavioural observations	Supervisor/ Manager	2004. Occupational Health and Safety Act, 1993 (Act No. 85 of 1993). National Environmental Management, Air Quality Act 39 of 2004.	None	Complete	None
		3	Climbing the stairs while carrying tools and chemicals	1	Falling and rolling down stairs	Safety	Carrying tools and chemical by hand while using stairs	None	Employees	Supervisor/ Manager	18 monthly, 8hrs	LTI	Risk assessment, tool 4 bucket	В	III P	Lowering and lifting chemicals and tools using a rope	Behavioural safety observations	Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993). National Environmental Management, Air Quality Act 39 of 2004.	None	Complete	None
				2	Struck by falling tools		chemicals	None	Employees	Supervisor/ Manager	18 monthly, 8hrs	LTI	Risk assessment, tool 4 bucket	В	III P	Lowering and lifting chemicals and tools using a rope		Supervisor/ Manager	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993). National Environmental Management, Air Quality Act 39 of 2004.	None	Complete	None
Transferring oil into the bulk tanks	N	1	Opening manhole covers	1	Trip and fall Struck by the floor	Safety	Floor plate removal Swinging lifted floor plate	None	Employees/	Supervisor/ Manager	6 Monthly, 8 hrs 6 Monthly, 8 hrs	Fatality Medical	Risk assessment 5	В	II P	Two man rule to be applied Proper rigging	Behavioural safety observations	Supervisor/ Manager Supervisor/	Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 - National Building Regulations and Building Standards Act 103 of 1977 Occupational Health and Safety Act, 1993	None		To be registered on IRM
		2	Slippery surface	1	plate		Oil spill	None	Contractors Employees/	Manager Supervisor/ Manager		Medical	Risk assessment, PPE 3	В	III P	Housekeeping	observations Behavioural safety observations	Manager Supervisor/ Manager	(Act No. 85 of 1993 - GN R1031 - GSR, 1996& GN R84 Construction Regulation, 2014	None		None
									madutics	aged							- Amband		Occupational Health and Safety Act, 1993 (Act No. 85 of 1993 - National Building Regulations and Building Standards Act 103 of 1977			

Handling of Gas bottles	N	1	Pressurized gas cylinder	1	Injury caused by	Safety	Pipe or connection rupture	None	Employees/	Supervisor/	3 monthly, 2hrs	LTI	Risk assessment and PPE	4 B	III	F	Task specific risk assessment	Behavioural safety	Supervisor/	Occupational Health	None	Complete	None
	1			1	exposure to gas				Contractors	Manager								observations	Manager	and Safety Act, 1993			
	1			1	under pressure															(Act No. 85 of 1993) -			
	1			1																Pressure			
	1			1																Equipment			
																				Regulations, 2009			
Testing of Fire Detectors	R	1	Working at heights	1	Falling from height	Safety	Missing a step while climbing up	Working at heights rescue training	Employees	Supervisor/	5 Weekly for 1 hr	LTI	Ladder training,	4 B	III	F	Task specific risk assessment	Behavioural safety	Supervisor/		None	Complete	None
	1			1			or down			Manager			inspections, safety					observations, inspections	Manager	and Safety Act, 1993			
	1			1									clearance for working at							(Act No. 85 of 1993) -			
	1				1	l							heights		1					GN R1031 -GSR,			