Weight %		Specific Requirements	Evidence	Score per Criteria
20%	Qualifications	Site Manager	Project manager with a PM/Technical qualification and 5 years management experience. B-Tech/BSc Mehcanical Eng. Submit the certified copies of the highest qualification and the CV demonstrating the relevant experience	6%
		Site Supervisor	National Diploma - Mech Eng. 3 years supervisory experience on WTP maintenance. Submit the certified copy of the highest qualification and the CV demonstrating the relevant experience	6%
		LMI registered rigger	5 years relevant experience with NQF level 3 qualification with trade test. Submit the certificate (copy) of the highest qualification and the CV demonstrating the relevant experience	3%
		Artisan should have miminum of N4 Cetrificate in Mechnical Engineering Filed , Trade test and 5 Years Experience in the Manitenance and installation of pumps, valves and pipes field.	N4 Qualification with Trade Test Certificate ( Red Seal)	3%
			Curricullumn Vitae with Experience in the maintenance and installation of pumps, valves and pipes	3%
		Welder	N4 Qualification with Trade Test Certificate ( Red Seal)	3%
			5 years relevant experience with NQF level 3 qualification with trade test. Submit the certificate (copy) of the highest qualification and the CV demonstrating the relevant experience	3%
		Planner to have Mechanical Engineering National Diploma with a trade test with 3 years experience in the planning environment with the knowledge of SAP, Pimavera and microsoft projects	N6 Mechanical Engineering Certificate	4%
			Curriculum Vitae with work experience in planning environment with the knowledge of SAP, Pimavera and microsoft projects	4%
60%	Plant Maintenance	Qualified Welding Procedure Specifications (WPS) and Welding Procedure Qualification Record (WPQR) - Mixed Material (pipes), 4mm to 16mm thickness.	Dissimilar Material Joint for Stainless Steel (Group 8.2) to Carbon Steel (Group 1.2)	10%
		Method Statement on the replacement of ash pumps in the ashplant pit	Servie provider to clearly indicate how he will go about replacing ash pumps in the ashplant pit	10%
		Availability of 3.5T or higher Forklift	Proof of ownership and valid load test certificate	5%
		Management of plant breakdowns and planned work	How will the service provider manage plant breakdown, planned work, quality and Programme amgangenet plan	5%
20%	Work expericence	ISO Certification	Certified valid ISO 3834-2 certificate indicating the following Design Codes (BS EN 13480; BS EN 13445 and P5500) and the following material groups (1, 4, 5, 6, 7, 8, 9, 10 & 11 according to ISO 15608).	10%
		ISO 9001:2015 Certificate	Certified valid certificate from reputable institutions	10%
		Rigging experience	4 x Rigging contracts/PO for the past 5 years. Client contact details, SOW details, order value.	10%
		Referral Letter of Work done previously on Mechanical environment	A minimum of 2 referrral letters from Companies where the Maintenance and installation of pumps, valves and pipes field. Work done on sites	5%
100%	Tech	nnical evaluation criteria threshold is 70%. Tenderers who	do not meet the threshold for functionality scoring will be disqualified and not be evaluated further.	100%

Compiled by : Molly Sithole

Date: 20 March 202

Signature