Annexure A: Technical Specifications for a 3-Year Contract: Service, Maintenance, Repair & Heavy Cleaning for Complete Phelophepa Kitchen & Diner Extraction Canopy Systems (095858467R)

Item No. Item Description Comply (Yes) / Not Comply (No) REPAIR, SERVICE AND MAINTAIN EQUIPMENT; TYPE: KITCHEN & DINER, LOCATION: PHELOPHEPA 1 AND 2; REMOVE ALL KITCHEN & DINER CANOPY NON-FIXED ITEMS HEAVY CLEAN, POLISH AND REPLACED ALL EXTRACTION SYSTEM FILITERS TO BE REMOVED, HEAVY CLEANED AND REPLACED MAIN EXTRACTION UNITS (INCL. MOTOR) TO BE CLEANED, SERVICED, MAINTAIN AND TESTED FOR FUNCTIONALITY REMOVE CEILING MOUNTED EXTRACTION FAN, HEAVY CLEAN AND RE-INSTALL TEST COMPLETE EXTRACTION INSTALLATIONS FOR CORRECT FUNCTIONALITY, MECHANICALLY AND ELECTRICALLY ISSUE A CLEANING COMPLIANCE CERTIFICATE (PER COACH NUMBER) IN ACCORDANCE WITH SANS 1850:2014 COACHES: 1) KITCHEN (PHELOPHEPA 1) - COACH NUMBER: 134071 (2 EXTRACTION CANOPIES) 3) DINER (PHELOPHEPA 2) - COACH NUMBER: 134071 (2 EXTRACTION CANOPIES) 4) DINER (PHELOPHEPA 2) - COACH NUMBER: 134090 (1 EXTRACTION CANOPIES)	(essession, try					
TYPE: KITCHEN & DINER, LOCATION: PHELOPHEPA 1 AND 2; REMOVE ALL KITCHEN & DINER CANOPY NON-FIXED ITEMS HEAVY CLEAN, POLISH AND REPLACED ALL EXTRACTION SYSTEM FILTERS TO BE REMOVED, HEAVY CLEANED AND REPLACED MAIN EXTRACTION UNITS (INCL. MOTOR) TO BE CLEANED, SERVICED, MAINTAIN AND TESTED FOR FUNCTIONALITY REMOVE CEILING MOUNTED EXTRACTION FAN, HEAVY CLEAN AND RE-INSTALL TEST COMPLETE EXTRACTION INSTALLATIONS FOR CORRECT FUNCTIONALITY, MECHANICALLY AND ELECTRICALLY ISSUE A CLEANING COMPLIANCE CERTIFICATE (PER COACH NUMBER) IN ACCORDANCE WITH SANS 1850:2014 COACHES: 1) KITCHEN (PHELOPHEPA 1) - COACH NUMBER: 134071 (2 EXTRACTION CANOPIES) 2) KITCHEN (PHELOPHEPA 2) - COACH NUMBER: 13484 (1 EXTRACTION CANOPIES) 3) DINER (PHELOPHEPA 1) - COACH NUMBER: 13484 (1 EXTRACTION CANOPIES)	Item No.	Item Description				
	095858467R	TYPE: XTCHEN & DINER, LOCATION: PHELOPHEPA 1 AND 2; REMOVE ALL KITCHEN & DINER CANOPY NON-FIXED ITEMS HEAVY CLEAN, POLISH AND REPLACED ALL EXTRACTION SYSTEM FILTERS TO BE REMOVED, HEAVY CLEANED AND REPLACED MAIN EXTRACTION UNITS (INCL. MOTOR) TO BE CLEANED, SERVICED, MAINTAIN AND TESTED FOR FUNCTIONALITY REMOVE CEILING MOUNTED EXTRACTION FAN, HEAVY CLEAN AND RE-INSTALL TEST COMPLETE EXTRACTION INSTALLATIONS FOR CORRECT FUNCTIONALITY, MECHANICALLY AND ELECTRICALLY ISSUE A CLEANING COMPLIANCE CERTIFICATE (PER COACH NUMBER) IN ACCORDANCE WITH SANS 1850:2014 COACHES: 1) KITCHEN (PHELOPHEPA 1) - COACH NUMBER: 135162 (2 EXTRACTION CANOPIES) 2) KITCHEN (PHELOPHEPA 2) - COACH NUMBER: 134071 (2 EXTRACTION CANOPIES) 3) DINER (PHELOPHEPA 1) - COACH NUMBER: 1434071 (2 EXTRACTION CANOPIES)				

SU	BN	٩IT	TΕΙ)

Name: Wade Arendsen Designation: Engineering Technician

Signature: Micudsen

Date: 20/08/2025