

KPA - AREA OF EVALUATION	OVERALL WEIGHT (%)	KPI - CRITERIA EVALUATION INDICATOR	MINIMUM CRITERIA EVALUATION REQUIREMENTS	SOURCE	%	SCORE SCALE						
Technical Requirements	35%				5%	Floor 6mth =1	Kick in 1 year	Average 1.5 years	Strech 2 years	Ceiling 3years		
		Company Establishment date	At least 3 years + in business industry	Provide Company profile indicating establishment date		0,0	0,0	3,0	4,0	5,0		
		Company workshop	The company must have a workshop with repair banches and overhead crane. Atleast 5 ton crane, industrial lathe, drilling machine, Pump test bay capable to test 112KW pumps	Provide address of the workshop and pictures. Before the award of the tender Eskom personal will physically confirm the workshop with all the requirements.	15%		Have no workshop			Have a fully equipped workshop with all the min workshop equipment		
						0,00			15,00			
							20%					
		Have maintained any submersible pumps ( Warman, Dragflow, Tsurumi, goodwin and Hippo pumps)	Provide proof of previous work on this pumps. Order number with contactable reference on the maintenance of the submersible pumps	20%	No work experience of submersible pumps	One work experience of submersible pumps	Two work experience of submersible pumps	Three work experience of submersible pumps	More than three work experience of submersible pumps			
					0,0	5,0	8,0	10,0	20,0			
		OEM (Original Equipment Manufacture) letter confirming the intend to support the company with original spares	Provide signed letter from the OEM (with the letter head of the OEM)	30%	It less than two signed letters from the OEM submitted		Submitted three signed letters from the OEM		Provide all five signed letters from the OEM			
					0,0		15,0		30,0			
		Company has 4 jobs done on electrical panels in less than a year ago	proof of work done on electrical panels. Order number with contactable reference on the maintenance of the submersible pumps control panels or any pump panels	10%	No work done	Only one work done more or less than a year ago	Only two work done more or less than a year ago	Only three work done more or less than a year ago	More than four work done more or less than a year ago			
					0,0	0,0	3,0	5,0	10,0			
		Two qualified mechanical artisan (fitter) with Trade test certification and atleast 4 years experience	Provide CV with experience and trade test certificate	10%	No attached copies	Attached CV with less than a year experience and trade test certificate or trade results record	Attached CV with two year experience and trade test certificate or trade results record	Attached CV with three year experience and trade test certificate or trade results record	Attached CV with four year experience and trade test certificate or trade results record			
					0,0	4,0	6,0	8,0	10,0			
		One qualified electrical artisan with Trade test certification and atleast 4 years experience	Certified copy of qualifications and appointment letters showing date of appointment	10%	No attached copies	Attached CV with less than a year experience and trade test certificate or trade results record	Attached CV with two year experience and trade test certificate or trade results record	Attached CV with three year experience and trade test certificate or trade results record	Attached CV with four year experience and trade test certificate or trade results record			
					0,0	4,0	6,0	8,0	10,0			
					100%							
	#REF!					0,0	4,0	6,0	8,0	10,0		

TAKE NOTE: TECHNICAL SUITABLE ONLY IF TOTAL SCORE IS EQUAL TO OR GREATER THAN 70 %. Eskom reserve right to consider and negotiate with supplier who score between 60-74%

#### CONTRACTOR

1
2
3
4
5
6

System Engineer

THAMI KHUMALO

SIGNATURE:

DATE:

2022/03/16

Project manager

SONWABO XABA

SIGNATURE:

DATE:

2022/03/16

