Reference	Rev	Page
DSG-318-087	2	15 of 15

Station/BU: Koeberg Operating Unit

## **APPENDIX A**

**Enquiry No: WCKBG2412SB(R2)** 

## **Supplier's Quality Programme Requirements**

TITLE: Provision of acoustic leak detection test (V-Service) to quantify valve leakage into

Condenser and contribution to PCLF on an as and when required basis at Nuclear Operating Unit **QUALITY LEVEL: Q3/L2** Tick (✓) as applicable YES NO ISO 9001 Quality Management System - Certified. ISO 9001 Quality Management System - Compliance. Formal Quality Assurance and inspection **Quality Assurance** Programme accepted by Eskom- such formal Programme control shall consist of the appropriate work procedures (e.g. procurement, receipt inspection, storage, handling processes, etc.) **ASME NQA-1** Quality Assurance Program Requirements for Nuclear Facilities Applications - Compliance IAEA-GSR-Part 2 The Management System for Facilities and Activities, - Compliance Documents which shall be prepared on implementing quality programme requirements: 1) Contract Quality Plan (ISO 10005) 2) Quality Control Plans (ISO 10005) 3) Data books for boilers, pressure vessels and alloy and high pressure/temperature pipe work systems Documents which shall be consulted on implementing quality programme requirements: 1) NEC Scope of Work 2) 2) Compiled by (Eskom): S Brown Date: 2024-04-23 Accepted by (Supplier): Date: