

ANNEXURE "B"-Stations Current and Vandalism Pictures

Kwesine.



Vandalized Building.





The building has been vandalized, and some of its components stripped off.






Inside the Building.



Toilet facilities within the building completely vandalized.




- Commuters waiting shelters.



The roofs of all platform canopies are vandalized.

Pilot.






Steel posts for walkway vandalized.



Suspended walkway vandalized.



Inside the Building completely vandalized.



- Commuters waiting shelters.



Platform canopies vandalized.



- **Cost Estimate (Repairs).**

Lindela.



Station main building.






The building is completely vandalized, and its components stripped off.



Inside the building is completely vandalized.



- Commuters' gates (Entrance/Exit).



Entrance/Exit point completely vandalized.

- Toilet Block.




Vandalised building.

Katlehong.
Station main building.




Building completely vandalized and its components stripped off.



- **Station Building** (Default Ticket sales signage).



The building is completely vandalized.



- Unmarked Building.



Building completely vandalized.

- Toilet Block.




Building completely vandalized.

- Commuters waiting shelters.



Platform canopies completely vandalized.




Wadeville



Vandalized Building.



Some parts of the building are burned.





- Toilet Block.



The building is vandalized and burned.



- Commuters waiting shelters.



Vandalized platform shelters.



Elsburg





Inside the building.



Broken window panes.

- Toilet Block.



Vandalized
Building.

- Commuters waiting shelters.



Vandalized Shelters.