



ANNEXURE A: PICTORIALS KEMPTON PARK

1. Ticket sales point.



2. Damaged ceiling in ticket office



3. Cracked platform floor surface.



4. Faded paint on steel structures





5. Leaking toilets.



6. Corrugated sheeting barrier on platform.



7. damaged floor in staff room.

8. Corrosion on platform bridge