



ANNEXURE A: PICTORIALS

		<p>Louvers to be changed</p> <p>Condition of the ablution facilities</p>
--	--	--



Fire damages due to non-compliance



Treat and paint rusted structures

Waterproofing and application of epoxy

Repair to Ceilings

Application of Epoxy

Replace missing balustrades

Replace damaged covers

Replace kitchenette cupboards

Strip old tiles and replace with new








Fencing





Ariel view



**ANNEXURE A: PICTURES ANNEXURE B: RE-ASSESSMENT REPORT ANNEXURE C:
BUSINESS CASE ANNEXURE D: PROJECT LIST ANNEXURE E: REQUEST FOR SERVICE
ANNEXURE F: PROCUREMENT PLAN ANNEXURE G: CONTRACT DATA ANNEXURE H: BILL
OF QUANTITIES**