

Title: NTCSA Live Line Offices at Cradock office- Eastern Grid lease transaction

Unique Identifier: **TBA**

Alternative Reference Number: **Optional**

Area of Applicability: **NTCSA BETHELSDORP, SPONDO ST, STRUANDALE, GQEBERHA FOR TELECOMMS, LINES AND SERVITUDES OFFICE.**

Documentation Type: **TECHNICAL EVALUATIONS**


Revision: **0**

Total Pages: **8**

Next Review Date: **Not applicable**

Disclosure Classification: **CONTROLLED DISCLOSURE**


**Compiled by:**



**Mabusi Khama  
Property Portfolio  
Officer**

Date: 19/03/2025....


**Supported by:**



**Fiona Walters  
Property Portfolio Manager**

Date: 19 March 2025.....

**Authorised by:**



**Phelokazi Nqwelo  
Middle Manager Real Estate**

Date: 19 March 2025.....

**CONTROLLED DISCLOSURE**

## EVALUATION CRITERIA

An occupancy certificate is mandatory, but tenderers will not be disqualified when submitting tenders, but documents must be provided before site evaluation is done, should they meet the minimum threshold stipulated in the technical evaluations

Technical evaluation criteria with weightings (in percentages) for goods or services as follows:

	Description of criteria elements	Scoring Criteria		Overall, Weight
1.	The building must be an existing structure that meets the minimum "B" grade standard (independent valuer certificate to be submitted) measuring approximately: Offices 580m <sup>2</sup> – 800m <sup>2</sup> Parking 36 Storage 35m <sup>2</sup> - 50m <sup>2</sup>	Confirmation provided	15%	15%
		Confirmation not provided but commitment to provide when required	7%	
		Not provided and no commitment to provide confirmation.	0%	
2.	Provide most recent service reports or certificate not older than December 2024 (for lifts where applicable, pumps where applicable, aircons, service doors, fire equipment, doors). The tenderer to indicate what is applicable to their building when submitting reports.	Provided – 100%	10%	10%
		Provided – 50% and above	5%	
		Provided less than 50%	0%	
3.	Provide condition assessment reports with valid compliance certificates where applicable not older than 3 (three) years.  Electrical and gas where applicable Plumbing. Civil and structural (structure, roofs, walls, drainage). Mechanical (lifts, aircons, fire equipment, doors - if not applicable, tenderer must confirm. Where there is a lift, compliance report not older than 1 year. In case of the building being vacant, the supplier must indicate and provide the last condition assessment reports and certificates.	Report with all certificates provided	10%	10%
		Report provided without certificates / older than 3 years	5%	
		No report / no certificate provided	0%	
4.	Property / building plans (as built drawings/floor plans for the leased premises)	Provided	10%	10%
		Not provided	0%	
5.	Preference for single building	Single building	10%	10%
		Multiple buildings in same complex. With access to roof	5%	
		Multi-buildings	2.5	
6.	Availability of Back-up power (Generator, UPS):	Available / commitment provided for installation and maintenance records.	10%	

### CONTROLLED DISCLOSURE

	Description of criteria elements	Scoring Criteria		Overall, Weight
	<ul style="list-style-type: none"> <li>In good working condition and connected for emergencies</li> <li>Record of maintenance to be provided.</li> <li>If not available, commitment (in writing) should be made to provide back-up power within 6 months of occupancy.</li> </ul>	Available / commitment provided for installation and without maintenance records.	5%	10%
		Unavailable and no commitment to install.	0%	
7.	Parking availability within the perimeter fence of the property <ul style="list-style-type: none"> <li>Approximately 36 x parking bays</li> </ul>	Covered secure parking	10%	10%
		Combination of secure covered parking and open parking bays	7.5%	
		Secure open parking bays	5%	
		No Parking or $\leq 26$ bays within the perimeter fence will be cause for disqualification	0%	
8.	Town/ City/ Nodal Centre: The property must be in close proximity to the current NTCSA offices in Bethelsdorp, Gqeberha Eastern Cape. The building must be in line of site or proximity to access Lovemore Heights radio (33°59'32.6"S, 25°31'13.9"E) and Lady Slipper radio site (33°53'10.3"S, 25°15'46.6"E) respectively via microwave link.  A property profile with print out of google maps indicating location of the property to be provided.	$\leq 3$ Km radius	15%	15%
		$>3\text{km} - \leq 5$ Km radius	10%	
		$>5$ km radius	5%	
9.	Backup water storage <ul style="list-style-type: none"> <li>In good working condition and connected for emergencies</li> <li>Record of maintenance to be provided.</li> <li>If not available, commitment (in writing) should be made to provide back-up water within 6 months of occupancy.</li> </ul>	Available / commitment provided for installation and maintenance records.	10%	10%
		Unavailable and no commitment to install.	0%	
<b>Total Score</b>				<b>100%</b>
<b>Minimum Threshold to be considered for further evaluation</b>				<b>70%</b>

Suppliers who achieve the minimum threshold will be subjected to a site evaluation.

#### **ON-SITE OBJECTIVE TECHNICAL EVALUATIONS**

	Measure	Description of criteria elements	Scoring Criteria	Score
1.				

#### **CONTROLLED DISCLOSURE**

When downloaded from the EDS database, this document is uncontrolled and the responsibility rests with the user to ensure it is in line with the authorised version on the database.

	Universal Accessibility	The accommodation's location supports service delivery objectives, accessible for the physically challenged and delivery of equipment & materials, i.e., availability of ramp, lift for multi-level building, bathroom wheelchair friendly, double-door from outside to allow wheelchair access and material delivery.	<p>Fully compliant (availability of ramp, lift for multi-level building, bathroom wheelchair friendly, double-door from outside to allow wheelchair access and material delivery) = 25%</p> <p>Fairly compliant (availability of ramp, lift for multi-level building, bathroom wheelchair friendly) = 15%</p> <p>Non-compliant = 0%</p>	25%
2.	Visual assessment	The premises are well maintained, with finishes as new. Adequate lighting, fixtures and fittings, paint work and flooring, do not require much work and premises can be occupied with minimal works.	<p>Property has no apparent defects. Appearance is as new = 25%</p> <p>Property exhibits superficial wear and tear, with minor defects and minor signs of deterioration to surface finishes = 15%</p> <p>Property exhibits significant wear and tear, with visible defects and significant signs of deterioration to surface finishes = 0%</p>	25%
3.	Security features	Secure perimeter fence (fully electrified or motion-sensored)	<p>Fully electrified or motion-sensored = 10%</p> <p>Not Electrified/Not energized – 5%</p> <p>None installed – 0%</p>	10%
4.	Security features	Security features such as security gates, outdoor lighting, burglar bars on windows, CCTV, security guards on premises/ entrance	<p>All (security gates, outdoor lighting, burglar bars on windows, CCTV, security guards on premises/ entrance) = 10%</p> <p>Partially = 5%</p> <p>None = 0%</p>	10%
5.	Security features	Availability of functional alarm system or commitment (in writing) to install within 6 months of occupancy.	<p>Installed or willingness to install = 5%</p> <p>Not installed or not functional = 0%</p>	5%

**CONTROLLED DISCLOSURE**

6.	Existing layout	Occupational Health & Safety compliant (emergency exits, fire extinguishers, adequate ventilation, adequate ablution facilities in line with national building regulations, adequate lighting).	Compliant - emergency exits, fire extinguishers, adequate ventilation, adequate ablution facilities in line with national building regulations = 25%	25%
			Non-compliant = 0%	
<b>TOTAL SCORING</b>				<b>100</b>

**There is no minimum threshold for the site evaluation, all suppliers who have been evaluated to this stage will proceed for further evaluation.**

**CONTROLLED DISCLOSURE**

When downloaded from the EDS database, this document is uncontrolled and the responsibility rests with the user to ensure it is in line with the authorised version on the database.