

Watershed Substation Refurbishment: Supply and installation of 275kV Tubular Busbar, 275kV Tubes post insulators, & Tubular busbar clamps**PART 4: SITE INFORMATION**

Document reference	Title	No of pages
C4	This cover page	1
	Site Information	1
Total number of pages		2

Watershed Substation Refurbishment: Supply and installation of 275kV Tubular Busbar, 275kV Tubes post insulators, & Tubular busbar clamps**PART 4: SITE INFORMATION**

Core clause 11.2(16) states

“Site Information is information which

- describes the Site and its surroundings and
- is in the documents which the Contract Data states it is in.”

In Contract Data, reference has been made to this Part 4 of the contract for the location of Site Information.

1. General description

Watershed Substation is located in the North West Province, in the vicinity of Lichtenburg. The location coordinates are 26.089924S 26.144909E.

All persons requiring access to site shall notify the Project Manager two (2) weeks before such access is required. The applicant shall provide proof of identification to the Project Manager with the site access application. A permit shall be issued and all contractors/visitors are required to visibly retain the permit at all times. All contractors must attend safety training and familiarization which will be provided by the Employers safety officer before commencement of any work on site. All contractors working at Watershed substation need to be security vetted

2. Existing buildings, structures, and plant & machinery on the Site

The works will be done in the 275kV yard only at Watershed Substation. Work will also be done inside the Substation at various sites(camps and 275kV yard).

3. Subsoil information

The general soil condition is turf/clay.

4. Hidden services

There are hidden services on site. Before any work can commence, it will be the responsibility of the contractor to ascertain from the “Engineering Assistant” the position of any existing services on site. Once these are indicated to the contractor they shall be deemed as “**known**”. Any costs incurred for the repairs to any “**known**” services shall be for the contractor’s account.

In the event that any services are found especially drainage pipes or cables, this must be reported to the Site Supervisor and Engineering Assistant immediately.

5. Other reports and publicly available information

Geotechnical Surveys has been issued with tender enquiry for contractor may need to be able to decide his method of working and programme.