
	SCOPE OF WORK To Rebuild Engines	Bulk Material Services
---	---	-------------------------------

APPENDIX A

Description	Technical Criterion	Scoring Criteria	Weight (%)
Track Record of the company			
Proven track record of successful provision of required services	Trade reference letters from clients where similar work has been conducted on Engine Repairs on earth moving equipment. (Provide signed documents)	20 = Reference letter submitted with more than 5 years of service to a particular client.	20
		0 = Reference letter not submitted	
Technical Skills, Capability and Resources			
Experience of key personnel (supervisor)	Provide Curriculum vitae (cv) and certificates/proof of qualification indicating relevant work and years of experience on earth moving equipment.	15 = CV submitted with more than 5 years of service	15
		0 = No CV or CV submitted with less than 5 years of service	
Experience of key personnel (artisan)	CV's of employees with a Red Seal qualified diesel mechanic certificate indicating relevant work and years of experience on earth moving equipment engine rebuilds. (Provide Trade test certificate)	15 = CV submitted with more than 5 years of service	15
		0 = CV not submitted or with less than 5 years of service	
		0 = Red Seal Trade test certificate not submitted.	
Resources	Premise's inspection of Availability of the relevant equipment for repairs and maintenance by ERI person to validate capability (Provide address and pictures of the workshop facilities) ERI representative will do physical inspections on the premises	20 = validation of the capability	20
		0 = No or inadequate capability	

Vumani Masondo 26 July 2022
Ngwako Ramoshaba 26/07/2022


ngwako ramoshaba

Engine Rebuild

Unique Identifier:

Revision: **1**Page: **1 of 2**

Technical compliance			
PI Insurance cover two million or greater to cover an engine loss	Insurance company cover letter with policy number	20 = Certificate or letter submitted to be verified by ERI	20
		0 = No certificate or letter submitted.	
Quality ISO 9001 certification	Provide valid certificates	10 = Valid certificate submitted	10
		0 = No certificate submitted.	
Total Weighted Score			100

Overall minimum threshold for qualification (70%)

Vumani Masondo 26 July 2022

Ngwako Ramoshaba 26 July 2022


ngwako ramoshaba

When downloaded from the document management system, this document is uncontrolled and the responsibility rests with the user to ensure it is in line with the authorised version on the system.

No part of this document may be reproduced without the expressed consent of the copyright holder, Eskom Rotek Industries SOC Ltd.