

BID No.: 10409720

BID Description: Replace and service roller shutter doors

Annexure C3.2 Scope of Work

Doors to be replaced

Two roller shutter doors to be replaced completely with new shaft and rollers small doors, at the poly plant and the workshop opposite the poly plant. Door motor limits to be readjusted.

Doors to be serviced

Three doors to be fully serviced, two at the Thickening plant and one door requires the workshop strap on the small door opening to be replaced. Door motor limits to be readjusted.



BID No.: 10409720

BID Description: Replace and service roller shutter doors





BID No.: 10409720

BID Description: Replace and service roller shutter doors





BID No.: 10409720

BID Description: Replace and service roller shutter doors



BID No.: 10409720

BID Description: Replace and service roller shutter doors



Annexure C4 – Site Information

Rand Water Panfontein is situated about 2-3km up the road from Rand Water Zuikerbosch

RAND WATER ZUIKERBOSCH

Vischagat Road, Three Rivers East

Vereeniging, 1939

GPS Coordinates: S 26° 41.520 and E 28° 00.061

THE IMPORTANCE OF WEARING PPE

Everyone accessing the plant will be expected to wear safety shoes, failure to which no access will be granted.

THE IMPORTANCE OF CARRYING YOUR DRIVER'S LICENSE

Everyone accessing the site using personal or company vehicles is requested to always carry their valid driver's license.

DATA SECURITY

The site complies with the principle of Personal Access to Information Act (PAIA) and as such all data collected will be treated with the utmost confidentiality and used solely for security and access control purposes.



BID No.: 10409720

BID Description: Replace and service roller shutter doors