

Annexure C3.2 Scope of Work –

The following must be done - PAC Sprinkler remedial work for Insurance coverage compliance

1 x Supply and install 150 MM Flow switch and Test Valve

2 x Supply and install Gauge Cocks

1 x Supply and install Water Motor Alarm Gong

1 x Supply and install 150 MM Gate Valve

Replace 85 painted Sprinkler Heads

Reinstate 2x Roof supports

Supply and Replace 1 x Incorrect Sprinkler Head

Supply and Replace 1 x damaged sprinkler Head

Drain and refill 2 x Sprinkler system

1x P & G

The successful supplier must submit a safety file and attend induction before work can commence.

After completion of the project the successful supplier arrange for inspection to be done by Automatic Sprinkler Inspection Bureau (ASIB)

Annexure C4 – Site Information

RAND WATER ZUIKERBOSCH –

Vischagat Road, Three Rivers East

Vereeniging, 1939

GPS Coordinates: S 26° 41.520 and E 28° 00.061

Working Hours

Mon-Thurs 07:00-16:00

Fri – 07:00-14:00

THE IMPORTANCE OF WEARING PPE

Everyone accessing the plant will be expected to wear safety shoes, failure to which no access will be granted.

THE IMPORTANCE OF CARRYING YOUR DRIVER'S LICENSE

Everyone accessing the site using personal or company vehicles is requested to always carry their valid driver's license.

VALID CAR DISCS ARE ESSENTIAL

Every company or personal vehicle accessing the site must have a valid car disc. The biometric system will scan and cross-reference these discs to ensure compliance with local regulations. Failure to have a valid car disc may result in the vehicle being refused entry.



BID No.: 10416868

BID Description: Sprinkler remedial work PAC Plant –

Rand Water Zuikerbosch

DATA SECURITY

The site complies with the principle of Personal Access to Information Act (PAIA) and as such all data collected will be treated with the utmost confidentiality and used solely for security and access control purposes.