

Tender Number: HOAC-EFQ-48228 for the Supply, Delivery and Installation and Commissioning of 3kV Traction Transformer and Auxiliary Transformer under the jurisdiction of Vereeniging Infra Depot for a once-off period.

Test for Functionality Responsiveness test to RFP

EVALUATION CATEGOTY	WEIGHT
Functionality	100
1. Experience from previous relevant projects (Experience in traction and auxiliary transformer electrical works)	40
2. Human resource capacity	30
3. Delivery lead time	30

CATEGORY A: TECHNICAL / PRACTICAL (70% Threshold)	Total score	Score distribution	Points
1. Experience from previous relevant projects (Experience in traction and auxiliary transformer electrical works)	40	No Response (score 0): Tenderer has submitted no information of previous work experience and no contactable reference relevant to this tender.	0
		(Score 16): Working experience of One successfully completed project and contactable references relevant to this tender.	40
		(Score 28): Working experience of Two successfully completed projects and contactable references relevant to this tender.	70
		(Score 36): Working experience of Three successfully completed projects and contactable references relevant to this tender document.	90
		(Score 40) Working experience of Four and more and contactable references relevant to this tender document.	100

2. Human resource capacity	30	No Response (score 0): Tenderer has no evidence of any team strength capacity.	0
		(Score 12): Tenderer has evidence of one (1) Project Manager (without PMP), one (1) Supervisor/Technician, one (1) Wireman, one (1) Safety Officer/Specialist, one (1) SHE Rep and six (6) workers/assistants.	40
		(Score 21): Tenderer has evidence of one (1) Project Manager (without PMP), one (1) Supervisor/Technician, two (2) Wiremen, one (1) Safety Officer/Specialist, one (1) SHE Rep, and eight (8) workers/assistants.	70
		(Score 27): Tenderer has evidence of one (1) Project Manager (with PMP), two (2) Supervisors/Technicians, two (2) Wiremen, one (1) Safety Officer/Specialist, one (1) SHE Rep, and ten (10) workers/assistants.	90
		(Score 30): Tenderer has evidence of one (1) Project Manager (with PMP), one (1) Project Engineer (with BEng. /BSc. /BTech), two (2) Supervisors/Technicians, two (2) Wiremen, one (1) Safety Officer/Specialist, one (1) SHE Rep, and twelve (12) workers/assistants.	100

3. Delivery Lead Time Gantt chart depicting step by step how work is going to be executed and commissioned.	30	No Response (score 0): The tenderer did not submit the program or indicate any timeframe.	0
		(Score 12): 12 months or more to complete the project With very low detail on Gantt chart.	40
		(Score 21): 10 to 11 months to complete the project With low detail on Gantt chart.	70
		(Score 27): 7 to 9 months to complete the project With moderate detail on Gantt chart.	90
		(Score 30) 6 months or less to complete the project With high detail on Gantt chart.	100